

MW-4

WHITE-DIVISION OF WATER RESOURCES
CANARY-CLIENT'S COPY
PINK-WELL DRILLER'S COPY

STATE OF NEVADA
DIVISION OF WATER RESOURCES

OFFICE USE ONLY

Log No. 90508

Permit No. _____

Basin 105



PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

WELL DRILLER'S REPORT

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 446070

1. OWNER Verizon Services Group ADDRESS AT WELL LOCATION less than 1 mile past Hwy 208 on 295, Fire Rd. on right side, Dirt Road to top of hill, 2 1/2 miles

MAILING ADDRESS P.O. Box 725 China, CA 91708

2. LOCATION NW 1/4 NE 1/4 Sec 23 T. 10N R. 01E Douglas County

PERMIT NO. 102100001070 Issued by Water Resources Parcel No. Subdivision Name

3. WORK PERFORMED

New Well Replace Recondition Domestic Irrigation Test

Deepen Abandon Other _____ Municipal/Industrial Monitor Stock

5. WELL TYPE

Cable Rotary RVC Air Other _____

6. LITHOLOGIC LOG

Material	Water Strata	From	To	Thickness
<u>Backfilled with Bentonite Chips</u>		<u>20'</u>	<u>118'</u>	<u>98'</u>
<u>Backfilled with Concrete Grout</u>		<u>0'</u>	<u>20'</u>	<u>20'</u>
<u>Backfilled hole and then removed top 5' of P.V.C. and then removed Flush Mount Vault</u>				

8. WELL CONSTRUCTION

Depth Drilled _____ Feet Depth Cased _____ Feet

HOLE DIAMETER (BIT SIZE)

From _____ To _____

_____ Inches _____ Feet _____ Feet

_____ Inches _____ Feet _____ Feet

_____ Inches _____ Feet _____ Feet

CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>2"</u>		<u>sch. 80 P.V.C.</u>	<u>0'</u>	<u>38'</u>

Perforations:

Type perforation Factory Cut

Size perforation Information Unavailable

From 38' feet to 118' feet

From _____ feet to _____ feet

Surface Seal: Yes No Seal Type: Neat Cement Cement Grout Concrete Grout

Depth of Seal _____

Placement Method: Pumped Poured

Gravel Packed: Yes No

From _____ feet to _____ feet

9. WATER LEVEL

Static water level: 99.45 feet below land surface

Artesian flow _____ G.P.M. _____ P.S.I.

Water temperature _____ °F Quality _____

10. DRILLER'S CERTIFICATION

This well was drilled under my supervision and the report is true to the best of my knowledge.

Name Phillip Clamer Boalt Longyear Contractor

Address P.O. Box 1000 Dayton, Nv. 89403 Contractor

Nevada contractor's license number issued by the State Contractor's Board: 0010157

Nevada driller's license number issued by the Division of Water Resources, the on-site driller: M-0148

Signed Phillip E. Clamer By driller performing actual drilling on site or contractor

Date 7-29-03

Date started 7-24-03

Date completed 7-24-03

7. WELL TEST DATA

TEST METHOD: Bailer Pump Air Lift

G.P.M.	Draw Down (Feet Below Static)	Time (Hours)

RECEIVED
 03 AUG - 5 AM 10:40
 STATE ENGINEERS OFFICE