

WHITE-DIVISION OF WATER RESOURCES
CANARY-CLIENT'S COPY
PINK-WELL DRILLER'S COPY

STATE OF NEVADA
DIVISION OF WATER RESOURCES

OFFICE USE ONLY	
Log No.	91803
Permit No.	
Basin	212

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

WELL DRILLER'S REPORT
Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 28814

1. OWNER BOB DENINO ADDRESS AT WELL LOCATION 6310 E LAKE MEAD
 MAILING ADDRESS P.O. Box 711 LAS VEGAS, NV
DALLAS TX 75221

2. LOCATION SE 1/4 SE 1/4 Sec. 22 T. 20 N/S R. 62 E CLARK County

PERMIT NO. 140-22-601-002 Issued by Water Resources Parcel No. Subdivision Name

3. WORK PERFORMED
 New Well Replace Recondition
 Deepen Abandon Other

4. PROPOSED USE
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock

5. WELL TYPE
 Cable Rotary RVC
 Air Other

6. LITHOLOGIC LOG

Material	Water Strata	From	To	Thickness
REMOVE WELL VAULT.				
ATTEMPT TO REMOVE CASINGS, WITH NO SUCCESS.				
PLUG WELL FROM BOTTOM TO TOP W/ NEAT CEMENT.				
DUNK/DWV RECEIVED				
NOV 11 2003				
LAS VEGAS OFFICE				

8. WELL CONSTRUCTION

Depth Drilled _____ Feet Depth Cased _____ Feet

HOLE DIAMETER (BIT SIZE)

From	To
_____ Inches	_____ Feet _____ Feet
_____ Inches	_____ Feet _____ Feet
_____ Inches	_____ Feet _____ Feet

CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)

Perforations:

Type perforation _____

Size perforation _____

From _____ feet to _____ feet

Surface Seal: Yes No Seal Type: Neat Cement Cement Grout Concrete Grout

Depth of Seal _____

Placement Method: Pumped Poured

Gravel Packed: Yes No

From _____ feet to _____ feet

9. WATER LEVEL

Static water level _____ feet below land surface

Artesian flow _____ G.P.M. _____ P.S.I.

Water temperature _____ °F Quality _____

10. DRILLER'S CERTIFICATION

This well was drilled under my supervision and the report is true to the best of my knowledge.

Name EAGLE DRILLING SERVICES Contractor

Address 7150 PLACID ST Contractor
LAS VEGAS, NV

Nevada contractor's license number issued by the State Contractor's Board 51266

Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2202

Signed [Signature] By driller performing actual drilling on site or contractor

Date 11/12/03

Date started 11/11/03 2003

Date completed 11/11/03 2003

7. WELL TEST DATA

TEST METHOD: Bailor Pump Air Lift

G.P.M.	Draw Down (Feet Below Static)	Time (Hours)

20
62
22



SECOR
INTERNATIONAL
INCORPORATED

www.secor.com

December 29, 2003
SECOR Job No. 20EL.29665.03

Ms. Shannon Harbour
State of Nevada
Division of Environmental Protection
1771 East Flamingo Road, Suite 121A
Las Vegas, NV 89119

Log 9/18/03

**RE: WELL ABANDONMENT REPORT
7-ELEVEN STORE NO. 29665
6310 EAST LAKE MEAD BOULEVARD
LAS VEGAS, NEVADA
FACILITY ID NO. 8-000421
PETROLEUM FUND ID NO.: 99-258**

Dear Ms. Harbour:

SECOR International Incorporated (SECOR) on behalf of its client, 7-Eleven, Incorporated, is providing this well abandonment report pursuant to Nevada Division of Environmental Protection correspondence dated July 7, 2003. Well abandonment activities were conducted by Eagle Drilling Services (Eagle) of Las Vegas, Nevada, a State of Nevada licensed driller.

On November 11, 2003, SECOR personnel observed the well abandonment of one well (MW-1) on-site (Figure 1). Since Eagle's attempts to remove the well casing failed, the well was filled with bentonite-cement grout and topped with cement. The top 8-inches of the casing and former well collar were filled in with cement and sealed flush with the parking lot surface. The well box and concrete well collar were chipped/drilled out and the debris from field activities was disposed in an off-site dumpster. An *Intent to Drill Card* and *Well Drillers Report* were submitted to the Nevada Division of Water Resources by Eagle.

If you have any questions regarding this matter, please contact the undersigned at (702) 798-3911.

Sincerely,
SECOR International Incorporated

Matthew Grandjean, C.E.M.
Project Manager

Attachments: Figure 1

cc: File:\ Ken Hilliard, 7-Eleven, Incorporated
Robert Thompson, NDWR, Las Vegas, NV

ENVIRONMENTAL CERTIFICATION JURAT

This Well Abandonment Report for 7-Eleven Store No. 29665 located at 6310 East Lake Mead Boulevard, Las Vegas, Nevada, has been prepared in accordance with Nevada Administrative Code (NAC), Chapter 459, Section 9717.

I hereby certify that I am responsible for the services described in this document and for the preparation of this document. The services described in this document have been provided in a manner consistent with the current standards of the profession and to the best of my knowledge comply with all applicable federal, state and local statutes, regulations and ordinances.

Approved by:




Matthew Grandjean, C.E.M.

Project Manager

Nevada Environmental Manager EM-1790 (Expires 03/08/04)

Date Signed: 1/5/04

MOUNT HOOD



LAKE MEAD BOULEVARD

MW-1

LEGEND:



MONITORING WELL LOCATION

WELL LOCATION APPROXIMATE



NOT TO SCALE

SECOR INTERNATIONAL
INCORPORATED

5755 SANDHILL ROAD, SUITE A
LAS VEGAS, NEVADA 89120

SITE PLAN

7-ELEVEN STORE NO. 29665
6310 EAST LAKE MEAD BOULEVARD
LAS VEGAS, NEVADA 89115

FIGURE: 1

DATE: 5/15/03

PROJECT NO:
20EL.29665.03