

OFFICE USE ONLY
 Log No. 96984
 Permit No. 40551
 Basin 212

PRINT OR TYPE ONLY
 DO NOT WRITE ON BACK

WELL DRILLER'S REPORT
 Please complete this form in its entirety in
 accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 27879

1. OWNER Mario Di Biase ADDRESS AT WELL LOCATION _____
 MAILING ADDRESS _____
 2. LOCATION SE 1/4 SE 1/4 Sec I T 22S N/S R 61 E Clark County
 PERMIT NO. 40551 Issued by Water Resources Parcel No. 177-01-802-004 Subdivision Name Equestrian Estates

3. WORK PERFORMED
 New Well Replace Recondition
 Deepen Abandon Other _____
 4. PROPOSED USE Qm DSB
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock
 5. WELL TYPE
 Cable Rotary RVC
 Air Other _____

6. LITHOLOGIC LOG

| Material | Water Strata | From | To | Thick-ness |
|----------------------------|--------------|------|----|------------|
| No Drill Rig Used | | | | |
| No Deepening | | | | |
| No Cleaning | | | | |
| Liner only with Pump truck | | | | |

RECEIVED
 05 MAY 25 AM 10:13
 STATE ENGINEERS OFFICE

DCNR/DWR
 RECEIVED
 MAR 28 2005

LAS VEGAS OFFICE

8. WELL CONSTRUCTION
 Depth Drilled _____ Feet Depth Cased _____ Feet
 HOLE DIAMETER (BIT SIZE)
 From _____ To _____
 _____ Inches _____ Feet _____ Feet
 _____ Inches _____ Feet _____ Feet
 _____ Inches _____ Feet _____ Feet
 CASING SCHEDULE

| Size O.D. (Inches) | Weight/Ft. (Pounds) | Wall Thickness (Inches) | From (Feet) | To (Feet) |
|--------------------|---------------------|-------------------------|-------------|-----------|
| 6.90 | PVCSR | | +1 | 587 |
| 6.1/4 | ID | | | |

Perforations:
 Type perforation Factory
 Size perforation .037 Sieve Type
 From 487 feet to 587 feet
 From _____ feet to _____ feet

Surface Seal: Yes No Seal Type:
 Neat Cement
 Cement Grout
 Concrete Grout
 Depth of Seal _____
 Placement Method: Pumped Poured
 Gravel Packed: Yes No
 From _____ feet to _____ feet

Date started 2/28/05, 20 ____
 Date completed 2/28/05, 20 ____

7. WELL TEST DATA

TEST METHOD: Bailer Pump Air Lift

| G.P.M. | Draw Down (Feet Below Static) | Time (Hours) |
|--------|-------------------------------|--------------|
| | | |
| | | |
| | | |
| | | |

9. WATER LEVEL
 Static water level _____ feet below land surface
 Artesian flow Approx 30 G.P.M. _____ P.S.I.
 Water temperature 60.1 °F Quality _____

10. DRILLER'S CERTIFICATION
 This well was drilled under my supervision and the report is true to the best of my knowledge.
 Name Vernon H. Dimick Contractor
 Address 5360 N. Bonita Vista St. Contractor
Las Vegas Nev 89149
 Nevada contractor's license number 10062
 issued by the State Contractor's Board
 Nevada driller's license number issued by the Division of Water Resources the on-site driller 552
 Signed V H Dimick
 By driller performing actual drilling on site or contractor
 Date 03-24-05