

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
Log No. 100639  
Permit No. \_\_\_\_\_  
Basin 212

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 37668

1 OWNER Clark County Parks & Community Services ADDRESS AT WELL LOCATION 201 Via Antinceidio  
MAILING ADDRESS 2601 East Sunset Road Henderson, NV 89015  
Las Vegas, NV 89120 Subdivision Name: Boulder Dam Park Tract 2 County: Clark

2 LOCATION sw 1/4 se 1/4 Sec 21 T 21S N/S R 63 E Latitude \_\_\_\_\_ UTM E \_\_\_\_\_  NAD 27  
PERMIT/WAIVER No. n/a 160-21-810-027 Longitude \_\_\_\_\_ N \_\_\_\_\_  NAD 83/WGS 84  
Issued by Water Resources Parcel No. \_\_\_\_\_

3 TYPE OF WELL Is this well being plugged because a replacement well was drilled? no Is there an existing well log? n/a  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock  
If yes, what is replacement well NO? \_\_\_\_\_ If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 81 Feet Depth Cased 81 Feet

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>2</u>	<u>.34</u>	<u>.25</u>	<u>81</u>	<u>0</u>

Existing Perforations:  
Type of perforation \_\_\_\_\_ machine slots  
Size of perforation 0.032  
From 0 feet to 81 feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforator used: \_\_\_\_\_

From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_

5 WATER LEVEL  
Static water level 8 feet below land surface  
Artesian flow n/a G.P.M. n/a P.S.I.  
Water temperature n/a °F Quality n/a

8 WELL PLUGGING MATERIALS

From	feet to	Material Used		
<u>0</u>	<u>81</u>	<u>neat cement</u>	<input checked="" type="checkbox"/> Pumped	<input type="checkbox"/> Poured
			<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
			<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
			<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
			<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
			<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured

Neat Cement Fluid Weight 96/6 lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 3/22/2006  
Date Completed 3/22/2006 2006 alg

6 Additional Notes or Comments

Neat cement tremie piped from bottom to top as casing was pulled

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Viking Drillers, Inc. Contractor  
Address 801 Northport Dr. Contractor  
W. Sacramento, CA 95691

Nevada contractor's license number issued by the State Contractor's Board 0034680

Nevada driller's license number issued by the Division of Water Resources, the on-site driller M-2091

Signed \_\_\_\_\_  
Date 8/4/06  
By driller performing actual drilling on site or contractor

DCNR/DWR  
RECEIVED

AUG 31 2006

LAS VEGAS OFFICE