


STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
Log No. 100791  
Permit No. \_\_\_\_\_  
Basin 213



PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 30359

1 OWNER Perini Const. ADDRESS AT WELL LOCATION 3600 S. Las Vegas Blvd.  
MAILING ADDRESS 6370 S. Polaris Las Vegas, NV  
Las Vegas, NV 89113 Subdivision Name: MGM City Center County: Clark

2 LOCATION NW ¼ SE ¼ Sec 20 T 21S N/S R 61 E Latitude See Attached UTM E  NAD 27  
PERMIT/WAIVER No. DW-1217 162-20-501-005 Longitude N  NAD 83/WGS 84  
Issued by Water Resources Parcel No. \_\_\_\_\_

3 TYPE OF WELL dewatering Is this well being plugged because a replacement well was drilled? no Is there an existing well log? \_\_\_\_\_  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock If yes, what is replacement well NOI? \_\_\_\_\_ If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 38 Feet Depth Cased 38 Feet

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
12	12.5	.5	0	38

Existing Perforations:  
Type of perforation \_\_\_\_\_ machine  
Size of perforation 0.032  
From 0 feet to 38 feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no

If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforator used:  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_

5 WATER LEVEL  
Static water level 22 feet below land surface  
Artesian flow n/a G.P.M. n/a P.S.I.  
Water temperature n/a °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS  
Material Used  
From 0 feet to 10 feet neat cement  Pumped  Poured  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  Pumped  Poured

6 Additional Notes or Comments

Well #3

Neat Cement Fluid Weight 90/5.2 lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 10-Aug  
Date Completed 10-Aug

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Viking Drillers Inc. Contractor  
Address 801 Northport Dr. Contractor  
W. Sacramento, CA 95691  
Nevada contractor's license number issued by the State Contractor's Board 0034680  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller M 2091  
M-9021  
Signed \_\_\_\_\_  
Date 9/8/2006

DCNR/DWR  
RECEIVED

SEP 15 2006

LAS VEGAS OFFICE