


**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**

**OFFICE USE ONLY**

Log No. 101772

Permit No. \_\_\_\_\_

Basin 212



PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 30438

1 OWNER CC Parks & Community Services  
MAILING ADDRESS 2601 East Sunset Road  
Las Vegas, NV 89120

ADDRESS AT WELL LOCATION 210 Via Antincendio  
Henderson, NV 89015  
Subdivision Name: Powerline Weir Crossing 3.3 County: Clark

2 LOCATION SW  $\frac{1}{4}$  SE  $\frac{1}{4}$  Sec 21 T 21S N/S R 63 E  
PERMIT/WAIVER No. dw-1214 160-21-810-027  
Issued by Water Resources Parcel No.

Latitude See Attached UTM E \_\_\_\_\_  NAD 27  
Longitude \_\_\_\_\_ N \_\_\_\_\_  NAD 83/WGS 84

3 TYPE OF WELL De-water  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? no  
If yes, what is replacement well NO? \_\_\_\_\_  
Is there an existing well log? \_\_\_\_\_  
If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 35 Feet Depth Cased 35 Feet

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
8	5.7	.332	0	35

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforator used: \_\_\_\_\_

Existing Perforations:

Type of perforation	Size of perforation	From	feet to	To	feet
machine	0.032	15	feet to	35	feet
			feet to		feet
			feet to		feet
			feet to		feet
			feet to		feet

Additional Perforations:

From	feet to	feet	Number of perfs per linear foot

5 WATER LEVEL  
Static water level 10 feet below land surface  
Artesian flow n/a G.P.M. n/a P.S.I.  
Water temperature n/a °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
0	feet to	10	neat cement	<input type="checkbox"/>	<input type="checkbox"/>
	feet to			<input type="checkbox"/>	<input type="checkbox"/>
	feet to			<input type="checkbox"/>	<input type="checkbox"/>
	feet to			<input type="checkbox"/>	<input type="checkbox"/>
	feet to			<input type="checkbox"/>	<input type="checkbox"/>

6 Additional Notes or Comments  
This is wells 7-9 of 14 on this Parcel

Neat Cement Fluid Weight 96/6 lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 9/27/2006  
Date Completed 9/27/2006

**OCN/DWR  
RECEIVED**

DEC 04 2006

**LAS VEGAS OFFICE**

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Viking Drillers Inc. Contractor  
Address 801 Northport Dr. Contractor  
West Sacramento, CA 95691  
Nevada contractor's license number issued by the State Contractor's Board 0034680  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller m-2091  
Signed \_\_\_\_\_  
Date 10/10/2006  
By driller performing actual drilling on site or contractor