


STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT



Log No. 101780  
Permit No. \_\_\_\_\_  
Basin 212

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 30436

1 OWNER ICC Parks & Community Services ADDRESS AT WELL LOCATION 210 Via Antincendio  
MAILING ADDRESS 2601 East Sunset Road Henderson, NV 89015  
Las Vegas, NV 89120 Subdivision Name: Powerline Weir Crossing 3.3 County: Clark

2 LOCATION SW  $\frac{1}{4}$  SE  $\frac{1}{4}$  Sec 21 T 21S N/S R 63 E Latitude See Attached UTM E  NAD 27  
PERMIT/WAIVER No. dw-1214 160-21-810-039 Longitude \_\_\_\_\_ N  NAD 83/WGS 84  
Issued by Water Resources Parcel No. \_\_\_\_\_

3 TYPE OF WELL Dewater Is this well being plugged because a replacement well was drilled? no Is there an existing well log? \_\_\_\_\_  
 Domestic  Irrigation  Test  Municipal/Industrial  Monitor  Stock If yes, what is replacement well NO? \_\_\_\_\_ If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 35 Feet Depth Cased 35 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
8	5.7	.332	0	35

Existing Perforations:  
Type of perforation machine  
Size of perforation 0.032  
From 15 feet to 35 feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforator used: \_\_\_\_\_

From	feet to	feet	Number of perfs per linear foot
From _____	feet to _____	feet	Number of perfs per linear foot _____
From _____	feet to _____	feet	Number of perfs per linear foot _____
From _____	feet to _____	feet	Number of perfs per linear foot _____
From _____	feet to _____	feet	Number of perfs per linear foot _____
From _____	feet to _____	feet	Number of perfs per linear foot _____
From _____	feet to _____	feet	Number of perfs per linear foot _____

5 WATER LEVEL  
Static water level 10 feet below land surface  
Artesian flow n/a G.P.M. n/a P.S.I.  
Water temperature n/a °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS  
Material Used  
From 0 feet to 10 feet neat cement  Pumped  Poured  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  Pumped  Poured

6 Additional Notes or Comments  
This is wells 17 and 18. These are the only 2 dewatering wells on this parcel.

Neat Cement Fluid Weight 96/6 lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 9/27/2006  
Date Completed 9/27/2006

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Viking Drillers Inc. Contractor  
Address 801 Northport Dr. Contractor  
West Sacramento, CA 95691  
Nevada contractor's license number \_\_\_\_\_  
issued by the State Contractor's Board 0034680  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller \_\_\_\_\_ m-2091  
Signed \_\_\_\_\_  
Date 10/10/2006

DCNR/DWR  
RECEIVED

DEC 04 2006

LAS VEGAS OFFICE

(Rev. 03-05)

USE ADDITIONAL SHEETS IF NECESSARY