


**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**



**OFFICE USE ONLY**  
Log No. 104361  
Permit No. \_\_\_\_\_  
Basin 212

**PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 30110

1 OWNER (Perini Const.) for Restaurant Ventures Nevada Inc  
MAILING ADDRESS 6370 S. Polaris - 3950 Las Vegas Blvd S.  
Las Vegas, NV 89119 - 100's

ADDRESS AT WELL LOCATION 3734 S. Las Vegas Blvd.  
Las Vegas, Nv  
Subdivision Name: MGM City Center County: Clark

2 LOCATION NW 1/4 SE 1/4 Sec 20 T 21S N/S/R 61 E  
PERMIT/WAIVER No. DW 1226 162-20-701-017  
Issued by Water Resources Parcel No.

Latitude E 766.00700 UTM E  NAD 27  
Longitude N-313.00500 N  NAD 83/WGS 84

3 Temp Dewatering TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? no  
If yes, what is replacement well NOI? \_\_\_\_\_

Is there an existing well log? Yes  
If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 39 Feet Depth Cased 39 Feet

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
12	12.5	.5	0	39

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforator used: \_\_\_\_\_

Existing Perforations:

Type of perforation	Size of perforation	From	To
machine	0.032	0	39

Type of perforator used:

From	feet to	feet	Number of perfs per linear foot

5 WATER LEVEL  
Static water level 24 feet below land surface  
Artesian flow na G.P.M. na P.S.I.  
Water temperature na °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	<input type="checkbox"/> Pumped	<input checked="" type="checkbox"/> Poured
0	10	10	neat cement	<input type="checkbox"/> Pumped	<input checked="" type="checkbox"/> Poured
				<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
				<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
				<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
				<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
				<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured

6 Additional Notes or Comments  
Well #16  
SEP 27 2007  
SEP 22 2007

Neat Cement Fluid Weight 90/5.2 lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 8/14/2007  
Date Completed 8/14/2007

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Viking Drillers Inc. Contractor  
Address 801 Northport Dr. Contractor  
W. Sacramento, CA 95691  
Nevada contractor's license number \_\_\_\_\_  
issued by the State Contractor's Board 0034680  
Nevada driller's license number issued by the \_\_\_\_\_  
Division of Water Resources, the on-site driller M-9021 2091  
Signed [Signature]  
Date 9/14/2007