

STATE OF NEVADA
 DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
 Log No. 105493
 Permit No. _____
 Basin 212

PRINT OR TYPE ONLY
 DO NOT WRITE ON BACK *Clark County*
 Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. _____

1 OWNER Public Right of Way on Mountain Vista Rd.
 MAILING ADDRESS 500 South Grand Central Parkway
Las Vegas, Nv 89101

ADDRESS AT WELL LOCATION Public Right of Way on Mountain Vista Rd.

2 LOCATION NE ¼ NW ¼ Sec 20 T 21S N/S R 62 E
 PERMIT/WAIVER No. DW-1266 16120199022
Issued by Water Resources Parcel No.

Subdivision Name: Emergency Sewer Repair County: Clark
 Latitude _____ UTM E NAD 27
 Longitude _____ N NAD 83/WGS 84

3 *temp decontaminating*
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock

Is this well being plugged because a replacement well was drilled? no
 If yes, what is replacement well NO? _____
 Is there an existing well log? yes
 If yes, what is NDWR well log #? _____

4 EXISTING WELL CONSTRUCTION
 Depth Drilled 30 Feet Depth Cased 30 Feet

7 WELL PLUGGING PROCEDURE
 Was well cleaned out to total depth? yes no

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
8	6	3/8	0	30

If well was not cleaned out to total depth, please explain why: _____
 Was the well contaminated? yes no
 Was the casing pulled? yes no
 Was the casing over drilled? yes no

Existing Perforations:
 Type of perforation machine slotted
 Size of perforation 0.032
 From 10 feet to 30 feet
 From _____ feet to _____ feet

If casing was left in place, please show where additional perforations were made:
 Additional Perforations:
 Type of perforator used:
 From _____ feet to _____ feet Number of perfs per linear foot _____
 From _____ feet to _____ feet Number of perfs per linear foot _____
 From _____ feet to _____ feet Number of perfs per linear foot _____
 From _____ feet to _____ feet Number of perfs per linear foot _____
 From _____ feet to _____ feet Number of perfs per linear foot _____
 From _____ feet to _____ feet Number of perfs per linear foot _____

5 WATER LEVEL
 Static water level 12 feet below land surface
 Artesian flow _____ G.P.M. _____ P.S.I.
 Water temperature _____ °F Quality _____

8 WELL PLUGGING MATERIALS

6 Additional Notes or Comments

Well was next to sewer pipe being repaired. Well was consumed by exavation and filled with concrete slurry to top of sewer pipe, then covered with compacted fill

From	feet to	Material Used	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
30	12	concrete slurry	<input checked="" type="checkbox"/>	<input type="checkbox"/>
12	surface	fill	<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>

Well #2 _____

Neat Cement Fluid Weight _____ lbs/gal
 Bentonite Grout _____ % bentonite
 Date Started 4/8/2008
 Date Completed 4/8/2008

DCNR/DWR RECEIVED
 MAY 12 2008
 LAS VEGAS OFFICE

9 DRILLER'S CERTIFICATION
 This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
 Name Viking Drillers Inc. Contractor
 Address 801 Northport Dr. Contractor
West Sacramento, CA 95691
 Nevada contractor's license number issued by the State Contractor's Board 0034680
 Nevada driller's license number issued by the Division of Water Resources, the on-site driller M-2091
 Signed _____
 Date 5/7/2008
By driller performing actual drilling on site or contractor

(Rev. 05-06)

USE ADDITIONAL SHEETS IF NECESSARY

Logs, 105492, 105493, 105494



VIKING DRILLERS, INC.


Dewatering Systems

801 Northport Drive
West Sacramento, CA 95691-2153
(916) 372-4993 • FAX (916) 372-1337
www.vikingdrillersinc.com
California License #476668



May 7, 2008

Tracy Geter
Nevada Division of Water Resources
400 Shadow Lane, Room 201
Las Vegas, NV 89106




Re: DW-1266 Well Completion Reports

Dear Tracy,

Per our conversation, enclosed are the Well Drillers Plugging Reports for the three (3) temporary dewatering wells drilled along the Public Right of Way on Mountain Vista Rd. for the Emergency Sewer Repair work. These wells were directly adjacent to the pipeline being repaired and during the repair work the wells were completely consumed. As a result, there were no wells to abandon. Additionally, because of the unpredictable timeline for this emergency repair work and the need to expedite construction, a NOI card for well abandonment was not filed. Once again, these wells were temporary dewatering wells.

Sincerely,



Sean LaChapelle
Area Manager