

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
Log No. 105499  
Permit No. \_\_\_\_\_  
Basin 212

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

*Clark County sly*

NOTICE OF INTENT NO. See Attached

1 OWNER Public Right of Way on Theme Rd.  
MAILING ADDRESS 500 South Grand Central Parkway  
Las Vegas, Nv 89101

ADDRESS AT WELL LOCATION Common Area South of Theme Rd.

2 LOCATION N 1/2 SE 1/4 Sec 15 T 21S N/S R 62 E  
PERMIT/WAIVER No. DW-1267 16115797011  
*Issued by Water Resources* *Parcel No.*

Subdivision Name: Emergency Sewer Repair County: Clark  
Latitude \_\_\_\_\_ UTM E  NAD 27  
Longitude \_\_\_\_\_ N  NAD 83/WGS 84

3 *temp decontaminating* TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? no  
If yes, what is replacement well NOI? \_\_\_\_\_

Is there an existing well log? yes  
If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 30 Feet Depth Cased 30 Feet

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
8	6	3/8	0	30

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no

Existing Perforations:  
Type of perforation machine slotted  
Size of perforation 0.032  
From 10 feet to 30 feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet

If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforator used:  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_

5 WATER LEVEL  
Static water level 18 feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS  
Material Used  
From 30 feet to 12 feet concrete slurry  Pumped  Poured  
From 12 feet to surface feet fill  Pumped  Poured  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  Pumped  Poured

6 Additional Notes or Comments

Well was next to sewer pipe being repaired. Well was consumed by exavation and filled with concrete slurry to top of sewer pipe, then covered with compacted fill

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 3/5/2008  
Date Completed 3/5/2008

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Viking Drillers Inc. Contractor  
Address 801 Northport Dr. Contractor  
West Sacramento, CA 95691  
Nevada contractor's license number issued by the State Contractor's Board 0034680  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller M-2091  
Signed \_\_\_\_\_  
By driller performing actual drilling on site or contractor  
Date 5/7/2008

DCNR/DWR RECEIVED  
MAY 12 2008  
LAS VEGAS OFFICE

USE ADDITIONAL SHEETS IF NECESSARY

(Rev. 05-06)


Logs 105496, 105497, 105498, 105499,  
105500, 105501, 105502



# VIKING DRILLERS, INC.


## Dewatering Systems

801 Northport Drive  
West Sacramento, CA 95691-2153  
(916) 372-4993 • FAX (916) 372-1337  
www.vikingdrillersinc.com  
California License #476668



May 7, 2008

Tracy Geter  
Nevada Division of Water Resources  
400 Shadow Lane, Room 201  
Las Vegas, NV 89106



Re: DW-1266 Well Completion Reports

Dear Tracy,

Per our conversation, enclosed are the Well Drillers Plugging Reports for the seven (7) temporary dewatering wells drilled along the Public Right of Way on Theme Rd and the Common Area south of Theme Rd. for the Emergency Sewer Repair work. These wells were directly adjacent to the pipeline being repaired and during the repair work the wells were completely consumed. As a result, there were no wells to abandon. Additionally, because of the unpredictable timeline for this emergency repair work and the need to expedite construction, a NOI card for well abandonment was not filed. Once again, these wells were temporary dewatering wells.

Sincerely

  
Sean LaChapelle  
Area Manager