

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY

Log No. 105920  
Permit No. \_\_\_\_\_  
Basin 139

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 61335

1 OWNER General Moly, Inc. ADDRESS AT WELL LOCATION Mt. Hope  
MAILING ADDRESS 2215 N. 5th Street  
Eiko, NV 89801 Subdivision Name: \_\_\_\_\_ County: Eureka

2 LOCATION NE 1/4 NE 1/4 Sec 3 T 21N N/S/R 50 E Latitude 39.721203 UTM E 557651  NAD 27  
PERMIT/WAIVER No. \_\_\_\_\_ Longitude 116.327359 N 4396821  NAD 83/WGS 84  
Issued by Water Resources Parcel No. \_\_\_\_\_

3 TYPE OF WELL Is this well being plugged because a replacement well was drilled? No Is there an existing well log? No  
 Domestic  Irrigation  Test  Municipal/Industrial  Monitor  Stock  
If yes, what is replacement well NOI? \_\_\_\_\_ If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 570 Feet Depth Cased \_\_\_\_\_ Feet

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>8</u>				

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforator used: \_\_\_\_\_

Existing Perforations:

Type of perforation	Size of perforation	From	feet to	feet
		From		

From	feet to	feet	Number of perfs per linear foot
From			

5 WATER LEVEL  
Static water level 63.4 feet below land surface  
Artesian flow NO G.P.M. N/A P.S.I.  
Water temperature \_\_\_\_\_ ° F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From	<u>570</u>	feet to	<u>15</u> feet	<input checked="" type="checkbox"/> Abandonite	<input type="checkbox"/> Poured
From	<u>15</u>	feet to	<u>10</u> feet	<input type="checkbox"/> 3/8" Chips	<input checked="" type="checkbox"/> Poured
From	<u>10</u>	feet to	<u>0</u> feet	<input type="checkbox"/> cement	<input checked="" type="checkbox"/> Poured
From		feet to		<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From		feet to		<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From		feet to		<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured

6 Additional Notes or Comments  
8" hole cleaned to 570. Abandonite slurry pumped from bottom to surface. Hole circ w/ abandonite grout. Fill up to 10' with 3/8" chips and plug neat cement to surface. Not a 10" hole as noted on intent. Hole is 8".  
Called 24 hour notice @ 8:00 a.m. 4/3/08 - Joe

Neat Cement Fluid Weight 12.6 lbs/gal  
Bentonite Grout 30 % bentonite  
Date Started 4/4/2008  
Date Completed 4/4/2008

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Eklund Drilling Company, Inc.  
Address PO Box 2748  
Eiko, NV 89803  
Nevada contractor's license number issued by the State Contractor's Board 0030823  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2230  
Signed Jason Poole By driller performing actual drilling on site or contractor  
Date 4/9/2008

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Eklund Drilling Company, Inc.  
Address PO Box 2748  
Eiko, NV 89803  
Nevada contractor's license number issued by the State Contractor's Board 0030823  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2230  
Signed Jason Poole By driller performing actual drilling on site or contractor  
Date 4/9/2008