

STATE OF NEVADA
 DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
 Log No. **106875**
 Permit No. _____
 Basin **212**

PRINT OR TYPE ONLY
 DO NOT WRITE ON BACK

Please complete this form in its entirety in
 accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. **33806**

1 OWNER Clark County Aviation ADDRESS AT WELL LOCATION McCarren Airport Terminal 3
 MAILING ADDRESS P. O. Box 11005, Las Vegas, NV 5757 Wayne Newton blvd, Las Vegas, NV
 Subdivision Name: _____ County: Clark

2 LOCATION NE ¼ NE ¼ Sec 34 T 21S N/S R 61 E Latitude 631911 UTM E NAD 27
 PERMIT/WAIVER No. DW 1243A 162-34-502-010 Longitude 486854.2 N NAD 83/WGS 84
 Issued by Water Resources Parcel No. _____

3 TYPE OF WELL Is this well being plugged because a replacement well was drilled? no Is there an existing well log? yes
 Domestic Irrigation Test Municipal/Industrial Monitor Stock If yes, what is replacement well NOI? _____ If yes, what is NDWR well log #? 103518

4 EXISTING WELL CONSTRUCTION
 Depth Drilled 51 Feet Depth Cased 50 Feet

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
6.5	3.6	.280	0	20

Existing Perforations:
 Type of perforation _____ Machine Slot _____
 Size of perforation _____ 0.032 _____
 From _____ 20 _____ feet to _____ 50 _____ feet
 From _____ feet to _____ feet

5 WATER LEVEL
 Static water level 28' feet below land surface
 Artesian flow _____ G.P.M. _____ P.S.I.
 Water temperature _____ ° F Quality _____

6 Additional Notes or Comments
Existing grade was 15' below original grade, pulled well casing, and vacuum well pack to -35 below original grade. (20' below existing grade) and poured cement to 5' from the surface.
 Location # 7409

7 WELL PLUGGING PROCEDURE
 Was well cleaned out to total depth? yes no
 If well was not cleaned out to total depth, please explain why: Casing was removed

Was the well contaminated? yes no
 Was the casing pulled? yes no
 Was the casing over drilled? yes no
 If casing was left in place, please show where additional perforations were made:
 Additional Perforations:
 Type of perforator used: _____

From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	
From	20	feet to	35	feet Cement Grout <input type="checkbox"/> Pumpe <input checked="" type="checkbox"/> Poured
From	feet to	feet		<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
From	feet to	feet		<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
From	feet to	feet		<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
From	feet to	feet		<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
From	feet to	feet		<input type="checkbox"/> Pumped <input type="checkbox"/> Poured

Neat Cement Fluid Weight _____ lbs/gal
 Bentonite Grout _____ % bentonite
 Date Started 8-20-08
 Date Completed 8-20-08

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Griffin Dewatering Corp. Contractor
 Address 536 E. Maitland St. Contractor
Ontario, CA 91761

Nevada contractor's license number issued by the State Contractor's Board C-23 0031246

Nevada driller's license number issued by the Division of Water Resources, the on-site driller M-1985

Signed _____
 By driller performing actual drilling on site Contractor
 Date 9-12-08

DCNR/DWR
 RECEIVED
 SEP 16 2008
 LAS VEGAS OFFICE