

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
Log No. 107234  
Permit No. \_\_\_\_\_  
Basin 212

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 33543

1 OWNER SEM materials Energy ADDRESS AT WELL LOCATION 3901 Ponderosa way  
MAILING ADDRESS 61205 Yale Ave #70 Las Vegas, NV 89118  
Tulsa, OK 74136-4216 Subdivision Name: \_\_\_\_\_ County: Clark

2 LOCATION SE 1/4 NE 1/4 Sec 31 T 21 N R 61 E Latitude 36.4.50.36N UTM E \_\_\_\_\_  NAD 27  
PERMIT/WAIVER No. 16231605001 Longitude 115.11.28.49W N \_\_\_\_\_  NAD 83/WGS 84

Issued by Water Resources Parcel No. \_\_\_\_\_

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? NO  
If yes, what is replacement well NOI? \_\_\_\_\_

Is there an existing well log? NO  
If yes, what is NDWR well log #? 16231605

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 19 Feet Depth Cased 19 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>2"</u>	<u>PVC</u>	<u>Sch 40</u>	<u>0</u>	<u>19</u>

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: casing was pulled and hole was drilled out to 19' the cemented to surface.

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no

If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforator used: \_\_\_\_\_

From	feet to	feet	Number of perfs per linear foot

Existing Perforations:  
Type of perforation Factory slot  
Size of perforation .020

From	feet to	feet	feet
	<u>9</u>	<u>19</u>	

5 WATER LEVEL  
Static water level None feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_


8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	<input type="checkbox"/> Pumped	<input checked="" type="checkbox"/> Poured
	<u>0</u>	<u>19</u>	<u>neat cement</u>		
				<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
				<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
				<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
				<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
				<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
				<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured

6 Additional Notes or Comments  
Casing was full of dirt casing was pulled out and hole was drilled out to 19' no water was encountered. hole was filled with cement.

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 11/12/08  
Date Completed 11/12/08

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Elite Drilling Inc. Contractor  
Address 4255 W. Post rd Contractor  
Las Vegas, NV 89118  
Nevada contractor's license number \_\_\_\_\_  
issued by the State Contractor's Board 0054931  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller M-1869  
Signed \_\_\_\_\_  
By driller performing actual drilling on-site or contractor  
Date 11/12/08



(Rev. 05-06)

USE ADDITIONAL SHEETS IF NECESSARY