STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 107928
Permit No.
Basin 212

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 34859

1 OWNER Public Right of Way (Clark County)
MAILING ADDRESS 5857 E. Flamingo Rd., LV, NV 89122

ADDRESS AT WELL LOCATION Cabana Rd (300' North of Flamingo Rd.)
Subdivision Name: Cabana Relief Interceptor County: Clark

2 LOCATION SW ¼ SE ¼ Sec 16 T 21S N/S R 62 E
PERMIT/WAIVER No. DW 1256 (Issued by Water Resources) 161-16-899-001 (Parcel No.)

Latitude
Longitude
UTM E SEE
N ATTACHED
☐ NAD 27
☐ NAD 83/WGS 84

3 temp dewatering
TYPE OF WELL
☐ Domestic ☐ Irrigation ☐ Test
☐ Municipal/Industrial ☐ Monitor ☐ Stock

Is this well being plugged because a replacement well was drilled? no
If yes, what is replacement well NO?

Is there an existing well log? yes
If yes, what is NDWR well log #?

4 EXISTING WELL CONSTRUCTION
Depth Drilled 30 Feet Depth Cased 30 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
8	6	3/8	0	30

Existing Perforations:
Type of perforation machine slot
Size of perforation 0.032

From	10	feet to	30	feet
From		feet to		feet
From		feet to		feet
From		feet to		feet
From		feet to		feet

5 WATER LEVEL
Static water level 8 feet below land surface
Artesian flow n/a G.P.M. P.S.I
Water temperature n/a °F Quality

6 Additional Notes or Comments

Abandoned all 6 wells

RECEIVED
JAN 23 2008

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? ☒ yes ☐ no
If well was not cleaned out to total depth, please explain why:

Was the well contaminated? ☐ yes ☒ no
Was the casing pulled? ☒ yes ☐ no
Was the casing over drilled? ☐ yes ☒ no
If casing was left in place, please show where additional perforations were made:
Additional Perforations:
Type of perforater used:

From		feet to		feet	Number of perfs per linear foot
From		feet to		feet	Number of perfs per linear foot
From		feet to		feet	Number of perfs per linear foot
From		feet to		feet	Number of perfs per linear foot
From		feet to		feet	Number of perfs per linear foot
From		feet to		feet	Number of perfs per linear foot

8 WELL PLUGGING MATERIALS

					Material Used		
From	0	feet to	10	feet	neat cement	☐ Pumpe	☒ Poured
From		feet to		feet		☐ Pumped	☐ Poured
From		feet to		feet		☐ Pumped	☐ Poured
From		feet to		feet		☐ Pumped	☐ Poured
From		feet to		feet		☐ Pumped	☐ Poured
From		feet to		feet		☐ Pumped	☐ Poured

Neat Cement Fluid Weight 94/5 lbs/gal
Bentonite Grout % bentonite
Date Started 12/20/2007
Date Completed 12/20/2007

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name Viking Drillers Inc (Contractor)
Address 801 Northport Dr. (Contractor)
West Sacramento, CA 95691
Nevada contractor's license number issued by the State Contractor's Board 0034680
Nevada driller's license number issued by the Division of Water Resources, the on-site driller M 2091
Signed (By driller performing actual drilling on site or contractor)
Date 1/16/2008

(Rev. 05-06)

USE ADDITIONAL SHEETS IF NECESSARY

Dewater

Log #'s 107928 to 107933

From: Matt Thompson(LV) [mthompson@ConverseConsultants.com]
Sent: Friday, December 28, 2007 3:04 PM
To: SLachapelle@VikingDrillersInc.com
Subject: GPS Locations for Cabana Rd. Las Vegas

Sean,
Here are the GPS coordinates you requested for the (6) well locations on Cabana Road, Las Vegas, Nevada. I will forward you the log diagrams pending their completion. If you have any other questions please feel free to contact me. Thanks.

	Northing	Easting
W-1:	26744313.2600	811962.89470
W-2:	26744372.2100	811957.40000
W-3:	26744383.6900	811936.66550
W-4:	26744425.5400	811945.89580
W-5:	26744509.2200	811954.52700
W-6:	26744605.4700	811962.96880

Matt Thompson
Staff Geologist
Converse Consultants
731 Pilot Road, Suite H
Las Vegas, NV 89119
phone (702) 269-8336 ext. 2065
cell (702) 506-2149
fax (702)269-8353
MThompson@converseconsultants.com
The information contained in this e-mail message (including attachments) is intended only for the personal and confidential use of the recipient(s) named above. This message (including attachments) may be work product and as such is privileged and confidential. If the reader of this message is not the intended recipient or agent responsible for delivering it to the intended recipient, you are hereby notified that you have received this document in error and that any review, dissemination, distribution, or copying of this message is strictly prohibited. If you have received this communication in error, please notify us immediately by e-mail, and delete the original message.

RECEIVED
JAN 23 2008

12/28/2007

THIS BORING LOG IS FOR VIKING'S INTERNAL PURPOSES ONLY. IT DOES NOT REPRESENT INFORMATION PROVIDED BY A SOILS ENGINEER.

LOG FOR BORING NO. I		JOB NAME: Converse Con			
DATE STARTED	DATE COMPLETED	LOGGED BY	DRILLED BY	TYPE OF DRILL RIG	JOB NO.
12-11-07	12-12-07	Ed	Ed	#36	1056
DEPTH OF HOLE	DIAMETER OF HOLE	CASING	PERFORATIONS	SAMPLING METHOD	ELEVATION
30'	24"	8"	20'		

LOCATION

DRILLERS NOTES:

19

DEPTH	SAMPLES	GRAPHIC	DESCRIPTION
			Street Base
			cobble
			Red clay
10'			silt sand
			hard clay
20'			
30'			
40'			
50'			
60'			
70'			
80'			
90'			
100'			

RECEIVED
JAN 23 2008

THIS BORING LOG IS FOR VIKING'S INTERNAL PURPOSES ONLY. IT DOES NOT REPRESENT INFORMATION PROVIDED BY A SOILS ENGINEER.

LOG FOR BORING NO. 5, 6, 2, 3, 4		JOB NAME: Converse Con			
DATE STARTED	DATE COMPLETED	LOGGED BY	DRILLED BY	TYPE OF DRILL RIG	JOB NO.
12-11-07	12-12-07	Ed	Ed	#36	1056
DEPTH OF HOLE	DIAMETER OF HOLE	CASING	PERFORATIONS	SAMPLING METHOD	ELEVATION
30'	24"	8"	20'		

LOCATION: see back

DRILLERS NOTES: 29

DEPTH	SAMPLES	GRAPHIC	DESCRIPTION
			Street & Base Rock
			cobble
			Red clay
10'			Silty sand
			hard red clay
20'			
30'			
40'			
50'			
60'			
70'			
80'			
90'			
100'			

RECEIVED
JAN 23 2008