

PRINT OR TYPE ONLY
 DO NOT WRITE ON BACK

WELL DRILLER'S REPORT

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

Permit No. _____
 Basin. Ø76

NOTICE OF INTENT NO. 60366

1. OWNER Debby Collins ADDRESS AT WELL LOCATION _____
 MAILING ADDRESS _____
325 STOCK
FERNLEY, NV

2. LOCATION SE ¼ N6 ¼ Sec 15 T 20 N5 R 24 E 140N County _____
 PERMIT NO. _____ Parcel No. 021-151-23 Subdivision Name _____
 Issued by Water Resources _____

3. WORK PERFORMED
 New Well Replace Recondition
 Deepen Abandon Other _____

4. PROPOSED USE
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock

5. WELL TYPE
 Cable Rotary RVC
 Air Other _____

6. LITHOLOGIC LOG

Material	Water Strata	From	To	Thickness
BROWN SAND-CLAY		0	8	8
BROWN CLAY-GRAVEL		8	61	53
BROWN SAND	X	61	68	7
GRAY SILTY CLAY		68	101	33
BROWN SANDY CLAY	X	101	112	11
BROWN CLAY		112	126	14
FRACTURED ROCK	X	126	146	19

39.60403°N
 119.26576°W NAD83

RECEIVED
 2008 OCT 24 PM 3:54
 STATE ENGINEERS OFFICE

N 39.604117
 W 119.264758 NAD27

8. WELL CONSTRUCTION
 Depth Drilled 146 Feet Depth Cased 146 Feet

HOLE DIAMETER (BIT SIZE)
 From 10 5/8 Inches To 0 Feet 146 Feet
 _____ Inches _____ Feet _____ Feet
 _____ Inches _____ Feet _____ Feet

CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>6 5/8</u>	<u>13</u>	<u>.188</u>	<u>+1</u>	<u>6</u>
<u>6 5/8</u>	<u>4</u>	<u>SDR21</u>	<u>6</u>	<u>146</u>

Perforations:
 Type perforation GRINDER CUT
 Size perforation .045" x 4"

From _____ feet to _____ feet
 From 126 feet to 146 feet
 From _____ feet to _____ feet
 From _____ feet to _____ feet
 From _____ feet to _____ feet

Surface Seal: Yes No Seal Type:
 Depth of Seal 5.3 ft Neat Cement
 Placement Method: Pumped Cement Grout
 Poured Concrete Grout

Gravel Packed: Yes No
 From 53 feet to 146 feet

Date started 24 Sep, 2008
 Date completed 25 Sep, 2008

7. WELL TEST DATA

TEST METHOD: Bailer Pump Air Lift

G.P.M.	Draw Down (Feet Below Static)	Time (Hours)
<u>9-11</u>		<u>2.0</u>

9. WATER LEVEL
 Static water level 60 feet below land surface
 Artesian flow _____ G.P.M. _____ P.S.I.
 Water temperature COLD °F Quality CLEAR

10. DRILLER'S CERTIFICATION
 This well was drilled under my supervision and the report is true to the best of my knowledge.

Name BLAIN DRILLING & PUMP CO. INC.
 Address P.O. Box 1255
Carson City, NV 89702

Nevada contractor's license number issued by the State Contractor's Board 46498
 Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2167

Signed Jack Watson
 By driller performing actual drilling on site or contractor
 Date 4 Oct 08