

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY 108883

Log No. _____
Permit No. _____
Basin 022

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. **63683**

1. OWNER **James & Ursula Reynolds**
MAILING ADDRESS **P.O. Box 17082**
Reno NV. 89511
ADDRESS AT WELL LOCATION **4840 Sierra County Rd.**
Reno
Subdivision Name: _____ County: **Washoe**

2. LOCATION **SE 1/4 SE 1/4 Sec 34 T18N R19E**
Latitude **39.37577** UTM E NAD 27
PERMIT/WAIVER NO. D0M08-019 Parcel No. **49-090-15** Longitude **119.82809** N NAD 83/WGS 84
Issued by Water Resources

3. TYPE OF WELL
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock
Is this well being plugged because a replacement well was drilled? Yes No
If yes, what is replacement well NOI? _____
Is there an existing well log? Yes No
If yes, what is NDWR well log #? _____

4. EXISTING WELL CONSTRUCTION
Depth Drilled **192** Feet Depth Cased **192** Feet

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
8 5/8	16	.188	0	192

Existing Perforations:
Type of perforation _____
Size of perforation _____
From _____ feet to _____ feet
From _____ feet to _____ feet

5. WATER LEVEL
Static water level: **180** feet below land surface
Artesian flow: _____ G.P.M. _____ P.S.I.
Water Temperature: _____ °F Quality _____

6. Additional Notes or Comments
No additional perforations were done per Tim Hunt at Division of Water Resources. The pump was removed prior to abandoning. The Roof of the pump house was removed to gain access to the well and pump.

Washoe Co. Permit #WL090047

39.375860°N
119.827060°W
NAD 27 (TA)

11 JUN 16 2009 9:11 AM

7. WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? Yes No
If well was not cleaned out to total depth, please explain why: _____

Was the well contaminated? Yes No
Was the casing pulled? Yes No
Was the casing over drilled? Yes No
If casing was left in place, please show where additional perforations were made:
Additional Perforations:
Type of perforator used:
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____

8. WELL PLUGGING MATERIALS
Material Used
Neat cement Pumped Poured
From **0** feet to **20** feet
Bentonit Pumped Poured
From **20** feet to **192** feet
From _____ feet to _____ feet Pumped Poured
From _____ feet to _____ feet Pumped Poured

Neat Cement Fluid Weight **15** lbs/gal
Bentonite Grout **20** % bentonite
Date Started **7-2-09**
Date Completed **7-2-09**

9. DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name **Bruce MacKay Pump & Well Service, Inc.**
(CONTRACTOR)
Address **1600 Mt. Rose Hwy**
(CONTRACTOR)
Reno, NV 89511
Nevada contractor's license number issued by the State Contractor's Board **23096**
Nevada driller's license number issued by the Division of Water Resources, the on-site driller **1790**
Signed R. Bruce MacKay
By driller performing actual drilling on site or contractor
Date **7-6-09**