

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY 110065
Log No.
Permit No.
Basin 101

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 63613

1. OWNER **Deutsche Bank c/o Washington Mutual** ADDRESS AT WELL LOCATION **2330 Lucas Rd.**
MAILING ADDRESS **7255 Baymeadows Way** **Fallon, NV 89406**
Jacksonville, FL 32256 Subdivision Name: _____ County: **Churchill**

2. LOCATION **SW¼SW¼ Sec18T19N/ R28E** Latitude **39.50706** UTM E _____ NAD 27
PERMIT/WAIVER NO. **008-112-30** Longitude **118.89359** N _____ NAD 83/WGS 84
Issued by Water Resources Parcel No. _____

3. TYPE OF WELL
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock
Is this well being plugged because a replacement well was drilled? Yes No
If yes, what is replacement well NOI? 63614
Is there an existing well log? Yes No
If yes, what is NDWR well log #? _____

4. EXISTING WELL CONSTRUCTION
Depth Drilled **19** Feet Depth Cased **19** Feet

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
8 5/8	18	.188	0	
6 5/8		pvc	2	19

Existing Perforations:
Type of perforation ? _____
Size of perforation _____
From _____ feet to _____ feet
From _____ feet to _____ feet

5. WATER LEVEL
Static water level: **None** _____ feet below land surface
Artesian flow: _____ G.P.M. _____ P.S.I.
Water Temperature: _____ °F Quality _____

6. Additional Notes or Comments
This well was a 6 5/8" well with a short piece of 8 5/8" casing around it. We pulled the 4' x 8 5/8" casing, perforated the 6 5/8" casing which shattered, and poured neat cement from top to bottom. The well was dry.

7. WELL PLUGGING PROCEDURE

Was well cleaned out to total depth? Yes No
If well was not cleaned out to total depth, please explain why:
There was well cap on the well with no vandalism showing.

Was the well contaminated? Yes No
Was the casing pulled? Yes No
Was the casing over drilled? Yes No

If casing was left in place, please show where additional perforations were made:
Additional Perforations: _____

Type of perforator used: **Mills Knife**
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____

8. WELL PLUGGING MATERIALS

Material Used			
From _____ feet to _____ feet		<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From _____ feet to _____ feet		<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From _____ feet to _____ feet		<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From _____ feet to _____ feet		<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From _____ feet to _____ feet		<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From _____ feet to _____ feet		<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured

Neat Cement Fluid Weight _____ lbs/gal
Bentonite Grout _____ % bentonite

Date Started **3/10/09**
Date Completed **3/10/09**

9. DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name **Bruce MacKay Pump & Well Service, Inc.**
(CONTRACTOR)

Address **1600 Mt. Rose Hwy**
(CONTRACTOR)

Reno, NV 89511

Nevada contractor's license number issued by the State Contractor's Board **23096**

Nevada driller's license number issued by the Division of Water Resources, the on-site driller **2299**

Signed [Signature]
By driller performing actual drilling on site or contractor

Date **3/10/2009**

39.507°N
118.893°W
NAD 27 D.D.

7000 NW 25 ST
MIAMI FL 33142