

**STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT**

OFFICE USE ONLY 110066
Log No. _____
Permit No. _____
Basin 103

**PRINT OR TYPE ONLY
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 64174

1 OWNER JOEY SBRAGIA
MAILING ADDRESS 650 PIKE ST
NW DAYTON NV 89403

ADDRESS AT WELL LOCATION 650 PIKE ST
DAYTON NV 89403
Subdivision Name: _____ County: Lyon

2 LOCATION NE 1/4 NW 1/4 Sec 23 T 18N N/S R 21 E
PERMIT/WAIVER No. 006-022-13
Issued by Water Resources Parcel No.

Latitude 39.24249°N UTM E _____ NAD 27
Longitude 119.59096°W N _____ NAD 83/WGS 84

3 TYPE OF WELL
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock

Is this well being plugged because a replacement well was drilled? _____
If yes, what is replacement well NOI? _____
Is there an existing well log? _____
If yes, what is NDWR well log #? _____

4 EXISTING WELL CONSTRUCTION
Depth Drilled 26 Feet Depth Cased 26 Feet

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
6 5/8	13.03	.188	0	26

If well was not cleaned out to total depth, please explain why: Well was drilled 10 ft further than 26 ft to clean out all the oil and contaminated debris that was encountered

Existing Perforations:
Type of perforation _____
Size of perforation _____
From _____ feet to _____ feet
From _____ feet to _____ feet

Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no
If casing was left in place, please show where additional perforations were made:
Additional Perforations:
Type of perforator used: n/a
From n/a feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____

5 WATER LEVEL
Static water level N/A feet below land surface
Artesian flow _____ G.P.M. _____ P.S.I.
Water temperature _____ °F Quality _____

8 WELL PLUGGING MATERIALS

From	feet to	Material Used	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
0	36	NEAT CEMENT	<input checked="" type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>

6 Additional Notes or Comments
A well was found on property and was contracted to clean out well by City of Lyon County. Called Ryan Clark when we encountered contamination of oil in well. Ryan suggested over drilling of contaminated well and plugging with neat cement to surface.

Neat Cement Fluid Weight _____ lbs/gal
Bentonite Grout 94/4 % bentonite
Date Started 05/09/2009
Date Completed 05/09/2009

2009 MAY 19 AM 10:53
STATE LAND MANAGEMENT DIVISION

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name CAPITAL CITY WELL DRILLING AND PUMP SERVICE INC.
Contractor
Address # 20 KIT KAT DRIVE
Contractor
CARSON CITY NV 89706
Nevada contractor's license number _____
issued by the State Contractor's Board 0055548
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 1905
Signed Michael Walsh
By driller performing actual drilling on site or contractor
Date 05/13/2009

39.243°N NAD27 D.D.
119.590°W