STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 110088
Permit No.
Basin 103

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 63541 ~~63538~~

1 OWNER STEVE SHAW
MAILING ADDRESS 5780 LAURREL DR
SW CARSON CITY , NV 89706

ADDRESS AT WELL LOCATION 5780 LAURREL DR
CARSON CITY, NV 89706
Subdivision Name: County: Carson City

2 LOCATION ~~NE~~ ¼ ~~SW~~ ¼ Sec 23 T 15N N/S R 20 E
PERMIT/WAIVER No. NE 010-092-03
Issued by Water Resources Parcel No.

Latitude 39.15198*N
Longitude 119.70178*W
UTM E N
☐ NAD 27 ☒ NAD 83/WGS 84

3 TYPE OF WELL
☒ Domestic ☐ Irrigation ☐ Test
☐ Municipal/Industrial ☐ Monitor ☐ Stock

Is this well being plugged because a replacement well was drilled? yes
If yes, what is replacement well NOI? 63539

Is there an existing well log? unk
If yes, what is NDWR well log #?

4 EXISTING WELL CONSTRUCTION
Depth Drilled 0 Feet Depth Cased 106 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
6 5/8	13.03	.156	0	106

Existing Perforations:
Type of perforation
Size of perforation
From feet to feet
From feet to feet
From feet to feet
From feet to feet
From feet to feet

5 WATER LEVEL
Static water level NONE - Dry feet below land surface
Artesian flow G.P.M. P.S.I
Water temperature HOT °F Quality POOR

6 Additional Notes or Comments

LOSS CIRCULATION WHILE DRILLING DEEPER
CASING FELL A FOOT PULLED OUT OLD CASING
ALL BUT 12' IN BOTTOM, PLACED BENTONITE PELLETS
IN BOTTOM, 23 BAGS, BACK FILLED WITH CLEAN FILL
DIRT TO 35' THEN PLACED NEAT CEMENT TO SURFACE

N 39.157070
W 119.700769 NAD27

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? ☐ yes ☒ no
If well was not cleaned out to total depth, please explain why: 12' of steel
6 5/8 broke off in well, casing was the perforated portion of well
well was being deepened and loss of circukation was encountered @ 120'

Was the well contaminated? ☐ yes ☒ no
Was the casing pulled? ☒ yes ☐ no
Was the casing over drilled? ☒ yes ☒ no
If casing was left in place, please show where additional perforations were made:
Additional Perforations:
Type of perforater used:
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot

8 WELL PLUGGING MATERIALS

					Material Used		
From	106	feet to	118	feet	bentonite chips	☐ Pumped	☒ Poured
From	106	feet to	35	feet	clean fill	☐ Pumped	☐ Poured
From	0	feet to	35	feet	neat cement	☐ Pumped	☒ Poured
From		feet to		feet		☐ Pumped	☐ Poured
From		feet to		feet		☐ Pumped	☐ Poured
From		feet to		feet		☐ Pumped	☐ Poured

Neat Cement Fluid Weight 94/6 lbs/gal
~~Bentonite Grout~~ ~~% bentonite~~
Date Started 01/21/2009
Date Completed 01/21/2009

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name CAPITAL CITY WELL DRILLING AND PUMP SERVICE INC
Contractor
Address # 20 KIT KAT DRIVE
Contractor
CARSON CITY , NV 89706
Nevada contractor's license number issued by the *State Contractor's Board* 0055548
Nevada driller's license number issued by the Division of Water Resources, the ~~on-site~~ *driller* 1905
Signed
By driller performing actual drilling on site or contractor
Date

(Rev. 05-08)

USE ADDITIONAL SHEETS IF NECESSARY