




Utility Shops - Please clear locations on this map marked with this symbol



Map Legend

- + Approximate Location of Soil Gas Monitoring Points - November 2009
- 11.5 Photo-ionization Detector Reading in PPM
- Proposed Location of New Monitoring Well - December 2009

Dig Permit Clearance Zones
 Tynhall Avenue & 2nd Street (Offut)
 Soil Gas Survey Nellis AFB, NV

96th CES Environmental Restoration, Nellis AFB, NV
 Valido Publico (102) 692-3042

Date: November 16, 2009

