

| | | | | | |
|---|-------------------------|---------------------|---------------------|-------------------------|-----------------|
| LOG FOR BORING NO. ¹⁰⁹ 107108 | | JOB NAME: LV PAVING | | | |
| DATE STARTED 3-31-2010 | DATE COMPLETED | LOGGED BY Ed | DRILLED BY Ed | TYPE OF DRILL RIG 31 | JOB NO. 5970 |
| DEPTH OF HOLE 30' | DIAMETER OF HOLE 24" | CASING 8" | PERFORATIONS 20' | SAMPLING METHOD | ELEVATION |

LOCATION: ST # 388+00, 389+00, 386+00

DRILLERS NOTES:

Not as much water
It's taking a longer
time for water to collect.

| DEPTH | SAMPLES | GRAPHIC | DESCRIPTION |
|-------|---------|---------|-------------------------------|
| 0' | | | Pavement & Base silty clay |
| 10' | | | silt silty clay |
| 20' | | | silty sand clay |
| 30' | | | |
| 40' | | | |
| 50' | | | |
| 60' | | | |
| 70' | | | |
| 80' | | | |
| 90' | | | |
| 100' | | | |

DCNR/DWR
RECEIVED
JUN 28 2010
LAS VEGAS OFFICE

APR 05 2010