

**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**

**OFFICE USE ONLY**  
Log No. 11776  
Permit No. \_\_\_\_\_  
Basin 212

**PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 35084

1 OWNER Southland EMP TR Thompson, John P TRS ADDRESS AT WELL LOCATION 225 N Lamb Blvd, Las Vegas NV  
MAILING ADDRESS c/o AV Tax Dept, P.O. Box 711 Dallas, TX  
75221 Subdivision Name: NA County: Clark

2 LOCATION NE ¼ SE ¼ Sec 31 T 20S N/S R 62 E Latitude 36d 10' 3.7" UTM E  NAD 27  
PERMIT/WAIVER No. NA 140-31-713-018 Longitude 115d 01' 37.6" N  NAD 83/WGS 84  
Issued by Water Resources Parcel No.

3 TYPE OF WELL Is this well being plugged because a replacement well was drilled? NO Is there an existing well log? No  
 Domestic  Irrigation  Test  Municipal/Industrial  Monitor  Stock If yes, what is replacement well NOI? \_\_\_\_\_ If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION

Depth Drilled 22 Feet Depth Cased 22 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>2.4</u>	<u>0.70</u>	<u>.15" - Sch 40 PVC</u>	<u>NA</u>	<u>NA</u>

7 WELL PLUGGING PROCEDURE

Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no

Existing Perforations:

Type of perforation	Machine Slotted
From <u>NA</u> feet to <u>NA</u> feet	<u>0.020"</u>
From _____ feet to _____ feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	

If casing was left in place, please show where additional perforations were made:  
Additional Perforations: NA

Type of perforator used: NA

From	feet to	feet	Number of perfs per linear foot
From _____	feet to _____	feet	_____
From _____	feet to _____	feet	_____
From _____	feet to _____	feet	_____
From _____	feet to _____	feet	_____
From _____	feet to _____	feet	_____

5 WATER LEVEL

Static water level NA feet below land surface  
Artesian flow No G.P.M. NA P.S.I.  
Water temperature NA °F Quality NA

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	Pumped	Poured
From <u>0</u>	feet to <u>22</u>	feet	<u>Cement Grout</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
From _____	feet to _____	feet	_____	<input type="checkbox"/>	<input type="checkbox"/>
From _____	feet to _____	feet	_____	<input type="checkbox"/>	<input type="checkbox"/>
From _____	feet to _____	feet	_____	<input type="checkbox"/>	<input type="checkbox"/>
From _____	feet to _____	feet	_____	<input type="checkbox"/>	<input type="checkbox"/>

Neat Cement Fluid Weight ~15 lbs/gal  
Bentonite Grout 5 % bentonite  
Date Started 5/20/2010  
Date Completed 5/20/2010

6 Additional Notes or Comments

Well ID: Unk-2

*DO NOT WRITE IN THESE SPACES*

*APR 24 2010*

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name David Messina - Yellow Jacket Drilling Services, LLC  
Contractor  
Address P.O. Box 801, Gilbert, AZ 85299  
Contractor

Nevada contractor's license number 0058304-A  
issued by the State Contractor's Board

Nevada driller's license number issued by the M-2378  
Division of Water Resources, the on-site driller

Signed [Signature]  
By driller performing actual drilling on site or contractor

Date 5/20/2010