

**STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT**

OFFICE USE ONLY
Log No. 111783
Permit No. _____
Basin 212

**PRINT OR TYPE ONLY
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 35084

1 OWNER Southland EMP TR Thompson, John P TRS ADDRESS AT WELL LOCATION 225 N Lamb Blvd, Las Vegas NV
MAILING ADDRESS c/o AV Tax Dept, P.O. Box 711 Dallas, TX
75221 Subdivision Name: NA County: Clark

2 LOCATION NE ¼ SE ¼ Sec 31 T 20S N/S R 62 E Latitude 36d 11' 54.8" UTM E NAD 27
PERMIT/WAIVER No. NA 140-31-713-018 Longitude 115d 08' 17.3" N NAD 83/WGS 84
Issued by Water Resources Parcel No.

3 TYPE OF WELL
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock
Is this well being plugged because a replacement well was drilled? NO
If yes, what is replacement well NOI? _____
Is there an existing well log? NO
If yes, what is NDWR well log #? _____

4 EXISTING WELL CONSTRUCTION
Depth Drilled 6 Feet Depth Cased 6 Feet
EXISTING CASING SCHEDULE

| Size O.D. (Inches) | Weight/Ft. (Pounds) | Wall Thickness (Inches) | From (Feet) | To (Feet) |
|--------------------|---------------------|--------------------------|-------------|-----------|
| <u>4.5</u> | <u>2.05</u> | <u>.24" - Sch 40 PVC</u> | <u>NA</u> | <u>NA</u> |

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why: _____
Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no
If casing was left in place, please show where additional perforations were made:
Additional Perforations: NA

Existing Perforations:
Type of perforation Machine Slotted
Size of perforation 0.020"

| From | feet to | feet | From | feet |
|-----------|-----------|-----------|-----------|-----------|
| <u>NA</u> | <u>NA</u> | <u>NA</u> | <u>NA</u> | <u>NA</u> |

Type of perforator used: NA

| From | feet to | feet | Number of perms per linear foot |
|-----------|-----------|-----------|---------------------------------|
| <u>NA</u> | <u>NA</u> | <u>NA</u> | <u>NA</u> |

5 WATER LEVEL
Static water level NA feet below land surface
Artesian flow No G.P.M. NA P.S.I.
Water temperature NA °F Quality NA

8 WELL PLUGGING MATERIALS

| From | feet to | feet | Material Used | <input type="checkbox"/> Pumped | <input type="checkbox"/> Poured |
|----------|----------|----------|---------------------|-------------------------------------|---------------------------------|
| <u>0</u> | <u>6</u> | <u>6</u> | <u>Cement Grout</u> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

6 Additional Notes or Comments
Well ID: Un Named & Unregistered
Unknown #1

Neat Cement Fluid Weight ~15 lbs/gal
Bentonite Grout 5 % bentonite
Date Started 5/24/2010
Date Completed 5/25/2010

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name David Messina - Yellow Jacket Drilling Services, LLC
Contractor
Address P.O. Box 801, Gilbert, AZ 85299
Contractor
Nevada contractor's license number 0058304-A
issued by the State Contractor's Board
Nevada driller's license number issued by the M-2378
Division of Water Resources, the on-site driller
Signed [Signature]
By driller performing actual drilling on site or contractor
Date 5/25/2010