

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 111786
Permit No. _____
Basin 212

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 35084

1 OWNER Southland EMP TR Thompson, John P TRS ADDRESS AT WELL LOCATION 225 N Lamb Blvd, Las Vegas NV
MAILING ADDRESS c/o AV Tax Dept, P.O. Box 711 Dallas, TX
75221 Subdivision Name: NA County: Clark

2 LOCATION NE ¼ SE ¼ Sec 31 T 20S N/S R 62 E Latitude 36d 11' 54.8" UTM E NAD 27
PERMIT/WAIVER No. NA 140-31-713-018 Longitude 115d 08' 17.3" N NAD 83/WGS 84
Issued by Water Resources Parcel No.

3 TYPE OF WELL Is this well being plugged because a replacement well was drilled? NO Is there an existing well log? NO
 Domestic Irrigation Test Municipal/Industrial Monitor Stock If yes, what is replacement well NOI? If yes, what is NDWR well log #?

4 EXISTING WELL CONSTRUCTION
Depth Drilled 5 Feet Depth Cased 5 Feet

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>4.5</u>	<u>2.05</u>	<u>.24" - Sch 40 PVC</u>	<u>NA</u>	<u>NA</u>

Existing Perforations:
Type of perforation Machine Slotted
Size of perforation 0.020"
From NA feet to NA feet
From _____ feet to _____ feet

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why:

Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no
If casing was left in place, please show where additional perforations were made:
Additional Perforations: NA
Type of perforator used: NA
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____

5 WATER LEVEL
Static water level NA feet below land surface
Artesian flow No G.P.M. NA P.S.I.
Water temperature NA °F Quality NA

8 WELL PLUGGING MATERIALS

From	feet to	Material Used	
<u>0</u>	<u>5</u>	<u>Cement Grout</u>	<input checked="" type="checkbox"/> Pumped <input type="checkbox"/> Poured
			<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
			<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
			<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
			<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
			<input type="checkbox"/> Pumped <input type="checkbox"/> Poured

6 Additional Notes or Comments
Well ID: Un Named & Unregistered unknown # 4

Neat Cement Fluid Weight ~15 lbs/gal
Bentonite Grout 5 % bentonite
Date Started 5/24/2010
Date Completed 5/25/2010

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name David Messina - Yellow Jacket Drilling Services, LLC
Contractor
Address P.O. Box 801, Gilbert, AZ 85299
Contractor
Nevada contractor's license number 0058304-A
issued by the State Contractor's Board
Nevada driller's license number issued by the M-2378
Division of Water Resources, the on-site driller
Signed [Signature]
By driller performing actual drilling on site or contractor
Date 5/25/10