



THIS BORING LOG IS FOR VIKING'S INTERNAL PURPOSES ONLY. IT DOES NOT REPRESENT INFORMATION PROVIDED BY A SOILS ENGINEER.

LOG FOR BORING NO.		JOB NAME: <i>LV Pavilion</i>			
DATE STARTED <i>6-30-10</i>	DATE COMPLETED	LOGGED BY <i>Ed</i>	DRILLED BY <i>Ed</i>	TYPE OF DRILL RIG <i># 31</i>	JOB NO. <i>5970</i>
DEPTH OF HOLE <i>40'</i>	DIAMETER OF HOLE <i>24"</i>	CASING <i>8"</i>	PERFORATIONS <i>20'</i>	SAMPLING METHOD	ELEVATION

LOCATION
283700

DRILLERS NOTES:
wellpoint didn't need to be pot holed

DEPTH	SAMPLES	GRAPHIC	DESCRIPTION
			<i>silt</i>
<i>10'</i>		<i>∇</i>	<i>silty clay</i> <i>moist</i> <i>silty sand</i> <i>silty clay</i>
<i>20'</i>			
<i>30'</i>			<i>silty sand</i>
<i>40'</i>			<i>clay</i>
<i>50'</i>			
<i>60'</i>			
<i>70'</i>			
<i>80'</i>			
<i>90'</i>			
<i>100'</i>			

DCNR/DWR
RECEIVED

SEP 13 2010

LAS VEGAS OFFICE

JUL 06 2010