

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
**WELL DRILLER'S PLUGGING REPORT**

**OFFICE USE ONLY**  
Log No. 113515  
Permit No. \_\_\_\_\_  
Basin \_\_\_\_\_

**PRINT OR TYPE ONLY**  
**DO NOT WRITE ON BACK**

*Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 34454

1 OWNER City of Las Vegas ADDRESS AT WELL LOCATION Public Right of way  
MAILING ADDRESS 400 stewart ave Las Vegas NV 89101  
Subdivision Name: \_\_\_\_\_ County: Clark

2 LOCATION SW ¼ NE ¼ Sec 34 T 20 S N/S R 61 E Latitude 36.10.80.14 UTM E  NAD 27  
PERMIT/WAIVER No. 139-34-699-002 Longitude 115.08.26.63 N  NAD 83/WGS 84  
Issued by Water Resources Parcel No.

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock  
Is this well being plugged because a replacement well was drilled? no  
If yes, what is replacement well NOI? \_\_\_\_\_  
Is there an existing well log? \_\_\_\_\_  
If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 30 Feet Depth Cased 30 Feet  
EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>2"</u>	<u>pvc</u>	<u>sch 40</u>	<u>0</u>	<u>30</u>

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_  
Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations:

Existing Perforations:  
Type of perforation \_\_\_\_\_  
Size of perforation \_\_\_\_\_

From	feet to	feet
From	feet to	feet

Type of perforator used:

From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot

5 WATER LEVEL  
Static water level 18 feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	Quich Grout	Pumpe	Poured
From <u>0</u>	feet to <u>30</u>	feet		<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
From	feet to	feet		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
From	feet to	feet		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
From	feet to	feet		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
From	feet to	feet		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

6 Additional Notes or Comments  
\_\_\_\_\_ pulled casing  
\_\_\_\_\_ filled from botton  
\_\_\_\_\_ To top Quich Grout  
**RECEIVED**  
**MAR 22 2011**  
**LAS VEGAS OFFICE**  
Las Vegas Plugging well 3 3811001

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 2/9/2011  
Date Completed 2/9/2011

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Eagle Drilling Services llc Contractor  
Address 7150 placid street Contractor  
Las Vegas Nv 89119  
Nevada contractor's license number issued by the State Contractor's Board 51266  
Nevada driller's license number issued by the Division of Water Resources the on-site driller 2097  
Signed \_\_\_\_\_  
By driller performing actual drilling on site of contractor  
Date 3/16/2011