

**STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT**

OFFICE USE ONLY
Log No. 114046
Permit No. _____
Basin φ73

**PRINT OR TYPE ONLY
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 67129

1 OWNER Richard Sorani ADDRESS AT WELL LOCATION Facility ID - 5-00082 MW: 17
MAILING ADDRESS P.O. Box 1030 810 Cornell Ave. Lovelock, NV
Lovelock, NV 89419 Subdivision Name: _____ County: Pershing

2 LOCATION NW ¼ SW ¼ Sec 26 T 27N N/S R 31 E Latitude 40°10'41.29"N UTM E NAD 27
PERMIT/WAIVER No. 001-128-15 Longitude 118°28'30.71"W N NAD 83/WGS 84
issued by Water Resources Parcel No.

3 TYPE OF WELL
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock
Is this well being plugged because a replacement well was drilled? No
If yes, what is replacement well NOI? _____
Is there an existing well log? _____
If yes, what is NDWR well log #? _____

4 EXISTING WELL CONSTRUCTION
Depth Drilled 31 Feet Depth Cased 31 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>4"</u>		<u>Sch 40</u>	<u>0</u>	<u>31</u>

Existing Perforations:

From	Type of perforation	Size of perforation	Slot	feet to	feet
From					

5 WATER LEVEL
Static water level _____ feet below land surface
Artesian flow _____ G.P.M. _____ P.S.I.
Water temperature _____ °F Quality _____

6 Additional Notes or Comments
Brake out bottom of well tremmie grout - Concrete top
2011 JUN 24 11:19 AM
SALESMAN

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why: _____

Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no
If casing was left in place, please show where additional perforations were made:
Additional Perforations: _____

Additional Perforations:

From	Type of perforator used:	Broke out Bottom	Number of perfs per linear foot
From			

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From				<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From				<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From				<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From				<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From				<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From				<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured

Neat Cement Fluid Weight 47 lbs/gal
Bentonite Grout 3 % bentonite
Date Started 28-Mar-11
Date Completed 29-Mar-11

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name Cascade Drilling, L.P. Contractor
Address 3632 Ormec Circle Contractor
Rancho Cordova, CA 95742
Nevada contractor's license number 73966
issued by the State Contractor's Board
Nevada driller's license number issued by the 1991
Division of Water Resources, the on-site driller
Signed [Signature]
By driller performing actual drilling on site or contractor
Date 25-Apr-11