

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 114087
Permit No. _____
Basin 212

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 35154

1 OWNER Bixby Land Co. ADDRESS AT WELL LOCATION 7600 Eastgate Road
MAILING ADDRESS 2211 Michelson Dr. Suite 500 Henderson, Nevada, 89011
Irvine, California 92612 Subdivision Name: TW-2 County: Clark

2 LOCATION SW $\frac{1}{4}$ NE $\frac{1}{4}$ Sec 11 T 22 N/SR 62 E Latitude 36.050508 UTM E NAD 27
PERMIT/WAIVER No. N/A 178-11-610-002 Longitude -115.019531 N NAD 83/WGS 84
Issued by Water Resources Parcel No.

3 TYPE OF WELL Is this well being plugged because a replacement well was drilled? No Is there an existing well log? No
 Domestic Irrigation Test Municipal/Industrial Monitor Stock If yes, what is replacement well NOI? _____ If yes, what is NDWR well log #? _____

4 EXISTING WELL CONSTRUCTION
Depth Drilled unkn Feet Depth Cased 40 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
2"		PVC Schedule 40	0	40

Existing Perforations:

Type of perforation	Factory Slotted
Size of perforation <u>0.02</u>	
From <u>25</u> feet to <u>40</u> feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	

5 WATER LEVEL
Static water level 33.6 feet below land surface
Artesian flow _____ G.P.M. P.S.I.
Water temperature _____ ° F Quality _____

6 Additional Notes or Comments
6-8-2011 The monitoring well casing separated at the first connection during the pulling.
6-13-2011 The monitoring well was over drilled and plugged using 3/8" bentonite chips.

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why: _____

Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no
If casing was left in place, please show where additional perforations were made:
Additional Perforations:
Type of perforator used: _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____

8 WELL PLUGGING MATERIALS
Material Used
From 0 feet to 1 feet Concrete Pumpe Poured
From 1 feet to 40 feet Benonite Chips Pumpe Poured
From _____ feet to _____ feet Pumped Poured

Neat Cement Fluid Weight _____ lbs/gal
Bentonite Grout _____ % bentonite
Date Started 6/8/2011
Date Completed 6/13/2011

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name Richard Erickson Contractor
Address 750 S Pilot Road Suite F Contractor
Las Vegas, Nevada 89119
Nevada contractor's license number _____
issued by the State Contractor's Board
Nevada driller's license number issued by the _____
Division of Water Resources, the on-site driller M-2409
Signed Richard Erickson
By driller performing actual drilling on site or contractor
Date 6/15/2011

DCNR/DWR
RECEIVED

JUN 16 2011

USE ADDITIONAL SHEETS IF NECESSARY

LAS VEGAS OFFICE

(Rev. 05-00)