

**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**

**OFFICE USE ONLY**  
Log No. 114407  
Permit No. \_\_\_\_\_  
Basin 212

**PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 35993

**1 OWNER** Public ROW  
MAILING ADDRESS 500 South Grand Central Pkwy  
Las Vegas, NV

ADDRESS AT WELL LOCATION Public ROW on Boulder Hwy  
at Boulder Hwy and Dahart St.  
Subdivision Name: \_\_\_\_\_ County: \_\_\_\_\_

**2 LOCATION** NW ¼ NW ¼ Sec 7 T 21S N/S/R 62 E  
PERMIT/WAIVER No. DW-1319A 16107199011  
Issued by Water Resources Parcel No.

Latitude 799700.68 UTM E  NAD 27  
Longitude 26753583.08 N  NAD 83/WGS 84

**3 TYPE OF WELL**  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? no  
If yes, what is replacement well NOI? \_\_\_\_\_  
Is there an existing well log? \_\_\_\_\_  
If yes, what is NDWR well log #? \_\_\_\_\_

**4 EXISTING WELL CONSTRUCTION**  
Depth Drilled 35 Feet Depth Cased 35 Feet

**7 WELL PLUGGING PROCEDURE**  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
8	6	3/8	0	35

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no

*Existing Perforations:*  
Type of perforation machine Slot  
Size of perforation \_\_\_\_\_  
From 15 feet to 35 feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet

*Additional Perforations:*  
Type of perforator used: \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_

**5 WATER LEVEL**  
Static water level \_\_\_\_\_ feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ ° F Quality \_\_\_\_\_

**8 WELL PLUGGING MATERIALS**

**6 Additional Notes or Comments**

Material Used			
From	feet to	feet	Material
0	10	feet	Concrete Grout 3/8s <input type="checkbox"/> Pumpe <input checked="" type="checkbox"/> Poured
			<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
			<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
			<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
			<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
			<input type="checkbox"/> Pumped <input type="checkbox"/> Poured

4th well Redrilled in Boulder Hwy Intersection

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 8/5/2011  
Date Completed 8/5/2011

Well A4 Redrill

**9 DRILLER'S CERTIFICATION**

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Viking Drillers Inc  
Contractor

Address \_\_\_\_\_

801 Northport Dr.  
Contractor

\_\_\_\_\_

Sacramento, CA 95691

\_\_\_\_\_

Nevada contractor's license number \_\_\_\_\_  
issued by the State Contractor's Board 0034680

\_\_\_\_\_

Nevada driller's license number issued by the \_\_\_\_\_  
Division of Water Resources, the on-site driller DEW-2361

\_\_\_\_\_

Signed \_\_\_\_\_  
By driller performing actual drilling on site or contractor

\_\_\_\_\_

Date 8/29/2011

\_\_\_\_\_

**DNWR/DWR  
RECEIVED  
SEP 01 2011**