

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 114434
Permit No. _____
Basin 212

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 35951

1 OWNER THRIFTY PAYLESS INC % REALEST ADDRESS AT WELL LOCATION 3846 W. SAHARA
MAILING ADDRESS TAX # 4111 PO BOX 3165 LAS VEGAS NV.
HARRISBURG PA 17105-3165 Subdivision Name: _____ County: CLARK
2 LOCATION SE 1/4 SE 1/4 Sec 06 T 21 N34R 61 E Latitude 36° 08' 43.39" N UTM E _____ NAD 27
PERMIT/WAIVER No. 16206813000 Longitude 115° 11' 29.9" W N _____ NAD 83/WGS 84
Issued by Water Resources Parcel No. _____

3 TYPE OF WELL
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock
Is this well being plugged because a replacement well was drilled? no
If yes, what is replacement well NOI? _____
Is there an existing well log? no
If yes, what is NDWR well log #? _____

4 EXISTING WELL CONSTRUCTION

Depth Drilled 31 Feet Depth Cased 31 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>2</u>		<u>0.440</u>	<u>0</u>	<u>31</u>

7 WELL PLUGGING PROCEDURE

Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why: _____

Existing Perforations:

From	Type of perforation	Size of perforation	feet to	feet
<u>11</u>	<u>MACHINE SLOT</u>	<u>.020</u>	<u>31</u>	

Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no
If casing was left in place, please show where additional perforations were made:
Additional Perforations:
Type of perforator used: NONE

From	feet to	feet	Number of perfs per linear foot

5 WATER LEVEL

Static water level 22.0 feet below land surface
Artesian flow _____ G.P.M. _____ P.S.I.
Water temperature _____ °F Quality _____

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	<input type="checkbox"/> Pumped	<input checked="" type="checkbox"/> Poured
<u>0</u>	<u>1</u>	<u>1</u>	<u>CONCRETE</u>		
<u>1</u>	<u>31</u>	<u>31</u>	<u>CEMENT GROUT</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>

6 Additional Notes or Comments

MWB

DCNR/DWR RECEIVED

AUG 22 2011

LAS VEGAS OFFICE

Neat Cement Fluid Weight 94 lbs/gal 5.2
Bentonite Grout _____ % bentonite
Date Started 8-8-2011
Date Completed 8-8-2011

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name EAGLE DRILLING Contractor
Address 7150 PLACID ST Contractor
LAS VEGAS NV. 89119
Nevada contractor's license number _____
issued by the State Contractor's Board 51266
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2357
Signed MWB
By driller performing actual drilling on-site or contractor
Date 8-8-2011