

**amended**  
 STATE OF NEVADA  
 DIVISION OF WATER RESOURCES  
**WELL DRILLER'S PLUGGING REPORT**

OFFICE USE ONLY  
 Log No. 114655  
 Permit No. \_\_\_\_\_  
 Basin 212

PRINT OR TYPE ONLY  
 DO NOT WRITE ON BACK

Please complete this form in its entirety in  
 accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 35060

1 OWNER Cal Nev Pipe Line, LLC ADDRESS AT WELL LOCATION Row Hacienda South of  
 MAILING ADDRESS 1100 Town & Country Rd 5290 S. Valley View Bl Las Vegas, NV 89119  
Orange, CA 92868 Subdivision Name: \_\_\_\_\_ County: Clark

2 LOCATION SW 1/4 NW 1/4 Sec 29 T 21 N R 61 E Latitude 36.0937 UTM E \_\_\_\_\_  NAD 27  
 PERMIT/WAIVER No. 160-29-299-037 Longitude -115.19993 N \_\_\_\_\_  NAD 83/WGS 84

Issued by Water Resources Parcel No.

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? \_\_\_\_\_  
 If yes, what is replacement well NOI? \_\_\_\_\_

Is there an existing well log? \_\_\_\_\_  
 If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION

Depth Drilled	Feet	Depth Cased	Feet
EXISTING CASING SCHEDULE			
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet) To (Feet)
<u>4.5</u>			<u>0</u> <u>85</u>

Existing Perforations:

Type of perforation	Size of perforation	From	feet to	feet

7 WELL PLUGGING PROCEDURE

Was well cleaned out to total depth?  yes  no  
 If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  yes  no  
 Was the casing pulled?  yes  no  
 Was the casing over drilled?  yes  no

If casing was left in place, please show where additional perforations were made:  
 Additional Perforations:

Type of perforator used:	From	feet to	feet	Number of perfs per linear foot

5 WATER LEVEL

Static water level 39.8 feet below land surface  
 Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
 Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	Pumped	Poured
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>

Neat Cement Fluid Weight 94 lbs/gal 5.2  
 Bentonite Grout 5 % bentonite

Date Started \_\_\_\_\_  
 Date Completed \_\_\_\_\_

6 Additional Notes or Comments

-not able to pull PVC casing.

**DCNR/DWR  
 RECEIVED**

**FEB 23 2012**

**LAS VEGAS OFFICE**

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Boart Longyear Co. Contractor  
 Address 1333 W. 9th St. Contractor  
Upland, CA 91786

Nevada contractor's license number issued by the State Contractor's Board 0021976  
 Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2438

Signed [Signature] BLV Contractor  
 By driller performing actual drilling on site or contractor  
 Date 2-21-12 Revised



**BOART  
LONGYEAR**

C57 #694686

**Boart Longyear E. I. Division**

1333 W. 9<sup>th</sup> St

Upland Calif. 91786

Tel: 909-946-1605 • Fax: 909-946-1608

[www.boartlongyear.com](http://www.boartlongyear.com)

To whom it may concern

*Attn: Steven Martinez*

Please replace previous submitted Well Reports with the revised ones attached as the owner information was incorrect.

Let me know if any questions

Thanks,

Mario Romero

909-946-1640

**DCNR/DWR  
RECEIVED**

FEB 23 2012

**LAS VEGAS OFFICE**