

**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**

**OFFICE USE ONLY**  
Log No. 114668  
Permit No. \_\_\_\_\_  
Basin 212

**PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 35992

1 OWNER Public ROW  
MAILING ADDRESS 500 South Grand Central Pkwy  
Las Vegas, NV

ADDRESS AT WELL LOCATION Public ROW on Boulder Hwy  
at Boulder Hwy and Dalhart St.

2 LOCATION NW 1/4 NW 1/4 Sec 7 T 21S N/S R 62 E  
PERMIT/WAIVER No. DW-1319A 16107199011  
*Issued by Water Resources Parcel No.*

Latitude 799401.93 UTM E  NAD 27  
Longitude 26754003.73 N  NAD 83/WGS 84

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? no  
If yes, what is replacement well NOI? \_\_\_\_\_

Is there an existing well log? \_\_\_\_\_  
If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 35 Feet Depth Cased 35 Feet

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
8	6	3/8	0	35

If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Existing Perforations:

Type of perforation	Size of perforation	From	To
machine Slot	15	feet to	35

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no

If casing was left in place, please show where additional perforations were made:

Additional Perforations:

Type of perforater used:	From	feet to	feet	Number of perfs per linear foot

5 WATER LEVEL  
Static water level \_\_\_\_\_ feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

6 Additional Notes or Comments

Material Used			
From <u>0</u> feet to <u>10</u> feet	Concrete Grout 3/8s	<input type="checkbox"/> Pumped	<input checked="" type="checkbox"/> Poured
From _____ feet to _____ feet	_____	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From _____ feet to _____ feet	_____	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From _____ feet to _____ feet	_____	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From _____ feet to _____ feet	_____	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From _____ feet to _____ feet	_____	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured

Well #11

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 9/20/2011  
Date Completed 9/20/2011

**DCNR/DWR  
RECEIVED  
DEC 05 2011  
LAS VEGAS OFFICE**

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Viking Drillers Inc  
Contractor

Address 801 Northport Dr.  
Contractor  
Sacramento, CA 95691

Nevada contractor's license number 0034680  
issued by the State Contractor's Board

Nevada driller's license number issued by the DEW-2361  
Division of Water Resources, the on-site driller

Signed \_\_\_\_\_  
By driller performing actual drilling on site or contractor

Date 11/9/2011

**USE ADDITIONAL SHEETS IF NECESSARY**

(Rev. 05-08)