

**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**

**OFFICE USE ONLY**  
Log No. 114670  
Permit No. \_\_\_\_\_  
Basin 212

**PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 35992

**1 OWNER** Public ROW  
MAILING ADDRESS 500 South Grand Central Pkwy  
Las Vegas, NV

ADDRESS AT WELL LOCATION Public ROW on Boulder Hwy  
at Boulder Hwy and Dalhart St.  
Subdivision Name: \_\_\_\_\_ County: \_\_\_\_\_

**2 LOCATION** NW 1/4 NW 1/4 Sec 7 T 21S N/S R 62 E  
PERMIT/WAIVER No. DW-1319A 16107199011  
*Issued by Water Resources Parcel No.*

Latitude 799500.41 UTM E  NAD 27  
Longitude 26753898.29 N  NAD 83/WGS 84

**3 TYPE OF WELL**  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? no  
If yes, what is replacement well NOI? \_\_\_\_\_

Is there an existing well log? \_\_\_\_\_  
If yes, what is NDWR well log #? \_\_\_\_\_

**4 EXISTING WELL CONSTRUCTION**  
Depth Drilled 35 Feet Depth Cased 35 Feet

**7 WELL PLUGGING PROCEDURE**  
Was well cleaned out to total depth?  yes  no

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
8	6	3/8	0	35

If well was not cleaned out to total depth, please explain why: \_\_\_\_\_  
Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no

*Existing Perforations:*  
Type of perforation machine Slot  
Size of perforation \_\_\_\_\_  
From 15 feet to 35 feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet

If casing was left in place, please show where additional perforations were made:  
*Additional Perforations:*  
Type of perforater used: \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_

**5 WATER LEVEL**  
Static water level \_\_\_\_\_ feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

**8 WELL PLUGGING MATERIALS**  
**Material Used**  
From 0 feet to 10 feet Concrete Grout 3/8s  Pumpe  Poured  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  Pumped  Poured

**6 Additional Notes or Comments**

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 9/20/2011  
Date Completed 9/20/2011

**Well #9**

**DCNR/DWR  
RECEIVED**

**DEC 05 2011**

**LAS VEGAS OFFICE**

**9 DRILLER'S CERTIFICATION**  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Viking Drillers Inc Contractor  
Address 801 Northport Dr. Contractor  
Sacramento, CA 95691  
Nevada contractor's license number 0034680  
issued by the State Contractor's Board  
Nevada driller's license number issued by the DEW-2361  
Division of Water Resources, the on-site driller  
Signed \_\_\_\_\_  
Date 9/9/2011  
By driller performing actual drilling on site or contractor

**USE ADDITIONAL SHEETS IF NECESSARY**

(Rev. 05-06)