

**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**

**OFFICE USE ONLY**  
Log No. 114676  
Permit No. \_\_\_\_\_  
Basin 212

**PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 36080

1 OWNER Mission Nevada, Inc. ADDRESS AT WELL LOCATION 1100 Foremaster Lane  
MAILING ADDRESS 1 W. Mayflower Ave. Las Vegas, NV  
N. Las Vegas, NV 89030 Subdivision Name: MW-3 County: Clark

2 LOCATION NW 1/4 NW 1/4 Sec 26 T 20S N/S R 61 E Latitude 36°11'05.27N UTM E  NAD 27  
PERMIT/WAIVER No. 13926102004 Longitude 115°07'51.27W N  NAD 83/WGS 84  
*Issued by Water Resources Parcel No.*

3 TYPE OF WELL Is this well being plugged because a replacement well was drilled? Is there an existing well log?  
 Domestic  Irrigation  Test  Stock  NO  Yes  
 Municipal/Industrial  Monitor  Stock If yes, what is replacement well NOI? If yes, what is NDWR well log #? 114502

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 25 Feet Depth Cased 25 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>2.375</u>		<u>SCH 40 PVC</u>	<u>0</u>	<u>10</u>

Existing Perforations:

Type of perforation	Factory Slotted
Size of perforation	0.02
From <u>10</u> feet to <u>25</u> feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	

5 WATER LEVEL  
Static water level 14.6 feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

6 Additional Notes or Comments  
Pulled casing, Cemented borehole with neat cement and concrete cap.  
  
**DCNR/DWR RECEIVED**  
JAN 24 2012  
  
**LAS VEGAS OFFICE**

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: Well was pulled

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforater used: NA

From	feet to	feet	Number of perfs per linear foot
From _____	feet to _____	feet	_____
From _____	feet to _____	feet	_____
From _____	feet to _____	feet	_____
From _____	feet to _____	feet	_____
From _____	feet to _____	feet	_____
From _____	feet to _____	feet	_____

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	
From <u>1</u>	feet to <u>25</u>	feet	Neat Cement	<input checked="" type="checkbox"/> Pumped <input type="checkbox"/> Poured
From _____	feet to _____	feet		<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
From _____	feet to _____	feet		<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
From _____	feet to _____	feet		<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
From _____	feet to _____	feet		<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
From _____	feet to _____	feet		<input type="checkbox"/> Pumped <input type="checkbox"/> Poured

Neat Cement Fluid Weight 94 / 5.8 lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 1/19/2012  
Date Completed 1/19/2012

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name WDC Exploration & Wells Contractor  
Address 739 W. Sunset Rd. Contractor  
Henderson, NV 89011  
Nevada contractor's license number issued by the State Contractor's Board 0012852  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2057  
Signed [Signature]  
By driller performing actual drilling on site or contractor  
Date 1/23/2012