

**STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT**

OFFICE USE ONLY
Log No. 115500
Permit No. 80313
Basin 101

**PRINT OR TYPE ONLY
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 67932 ✓

1 OWNER Dan and Anne Fagundes
MAILING ADDRESS 830 Wade Lane
Fallon, NV 89406
Issued by Water Resources Parcel No. 008-492-04

ADDRESS AT WELL LOCATION 5155 Reno HWY
Fallon, NV 89406f
Subdivision Name: _____ County: Churchill

2 LOCATION SE ¼ NE ¼ Sec 29 T 19N N/S/R 28 E
PERMIT/WAIVER No. 80313 008-492-04

Latitude UTM E 0340148 NAD 27
Longitude N 4371930 NAD 83/WGS 84

3 TYPE OF WELL
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock

Is this well being plugged because a replacement well was drilled? Yes
If yes, what is replacement well NOI? 67931
Is there an existing well log? Yes
If yes, what is NDWR well log #? 8378

4 EXISTING WELL CONSTRUCTION

Depth Drilled	Feet	Depth Cased	Feet
EXISTING CASING SCHEDULE			
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	To (Feet)
<u>10 5/8</u>		<u>.188</u>	<u>40</u>

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why: _____
Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no

Existing Perforations:

Type of perforation	Size of perforation	From	To
	<u>5/32</u>	<u>24</u> feet	<u>40</u> feet
		_____ feet	_____ feet
		_____ feet	_____ feet
		_____ feet	_____ feet
		_____ feet	_____ feet

If casing was left in place, please show where additional perforations were made:
Additional Perforations:

Type of perforator used:	From	feet to	feet	Number of perfs per linear foot
	_____	_____	_____	_____
	_____	_____	_____	_____
	_____	_____	_____	_____
	_____	_____	_____	_____
	_____	_____	_____	_____

5 WATER LEVEL
Static water level _____ feet below land surface
Artesian flow _____ G.P.M. _____ P.S.I.
Water temperature _____ °F Quality _____

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	<input checked="" type="checkbox"/> Pumped	<input type="checkbox"/> Poured
<u>0</u>	<u>40</u>	<u>feet</u>	<u>Neat Cement</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
_____	_____	_____	_____	<input type="checkbox"/>	<input type="checkbox"/>
_____	_____	_____	_____	<input type="checkbox"/>	<input type="checkbox"/>
_____	_____	_____	_____	<input type="checkbox"/>	<input type="checkbox"/>
_____	_____	_____	_____	<input type="checkbox"/>	<input type="checkbox"/>
_____	_____	_____	_____	<input type="checkbox"/>	<input type="checkbox"/>

6 Additional Notes or Comments
Well is in a pump house next to a milk barn.
Unable to set the rig up over the hole to pull casing.
Ran 1" trimmy washed in to 32"
Hit solid bottom, pumped neat cement from bottom up.

Neat Cement Fluid Weight 14.5 lbs/gal
Bentonite Grout _____ % bentonite
Date Started 3/17/2012
Date Completed 3/17/2012

Replaced by well log # 115499

RECEIVED
2012 MAY -7 PM 1:10
STATE ENGINEERS OFFICE

39.484011° N
118.858661° W
NAD 27

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name Welsco Drilling Corp Contractor
Address P.O. Box 888 Contractor
Fallon, NV 89406
Nevada contractor's license number issued by the State Contractor's Board 11752
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2199
Signed [Signature] By driller performing actual drilling on site or contractor
Date 3/17/2012