

**STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT**

OFFICE USE ONLY
Log No. 115601
Permit No. _____
Basin 212

**PRINT OR TYPE ONLY
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 36524

1 OWNER CV propco llc ADDRESS AT WELL LOCATION 3680 Tropicana ave Las Vegas NV
MAILING ADDRESS 1505 S pavilion Center DR
Las Vegas NV 89135 Subdivision Name: _____ County: Clark

2 LOCATION SW $\frac{1}{4}$ SW $\frac{1}{4}$ Sec 20 T 21S N/S R 61 E Latitude 36.06.04.48 UTM E NAD 27
PERMIT/WAIVER No. 8-0001807 Parcel No. 162-20-401-009 Longitude 115.11.17.77 N NAD 83/WGS 84
Issued by Water Resources

3 TYPE OF WELL
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock
Is this well being plugged because a replacement well was drilled? no
If yes, what is replacement well NOI? _____
Is there an existing well log? yes
If yes, what is NDWR well log #? 105723

4 EXISTING WELL CONSTRUCTION
Depth Drilled 40 Feet Depth Cased 40 Feet

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
4"	pvc	sch 40	0	40

Existing Perforations:
Type of perforation _____
Size of perforation _____
From _____ feet to _____ feet
From _____ feet to _____ feet
From _____ feet to _____ feet
From _____ feet to _____ feet

5 WATER LEVEL
Static water level 32 feet below land surface
Artesian flow _____ G.P.M. _____ P.S.I.
Water temperature _____ °F Quality _____

6 Additional Notes or Comments
remore well box
pulled casing
filled from botton
To top Bentonite and Concrete
0031207 well 5

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why: _____

Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no
If casing was left in place, please show where additional perforations were made:
Additional Perforations:
Type of perforater used: _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____

8 WELL PLUGGING MATERIALS
Material Used
From 0 feet to 11 feet concrete Pumpe Poured
From 11 feet to 40 feet Bentonite Pumpe Poured
From _____ feet to _____ feet Pumped Poured

Neat Cement Fluid Weight _____ lbs/gal
Bentonite Grout _____ % bentonite
Date Started 8/2/2012
Date Completed 8/3/2012

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name Eagle Drilling Services llc Contractor
Address 7150 placid street Contractor
Las Vegas Nv 89119
Nevada contractor's license number _____
issued by the State Contractor's Board _____ 51266
Nevada driller's license number issued by the _____
Division of Water Resources on-site driller _____ 2097
Signed _____
By driller performing actual drilling on site or contractor
Date 8/3/2012

**DCNR/DWR
RECEIVED**

USE ADDITIONAL SHEETS IF NECESSARY

AUG 08 2012

LAS VEGAS OFFICE