

**STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT**

OFFICE USE ONLY
Log No. 116153
Permit No. _____
Basin _____

**PRINT OR TYPE ONLY
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. N/A

1 OWNER County of Clark (Administrative) ADDRESS AT WELL LOCATION 300 S Casino Center Blvd
MAILING ADDRESS 500 S. Grand Pkwy
Las Vegas, NV 89155 Subdivision Name Correction Center County: Clark

2 LOCATION SE 1/4 NW 1/4 Sec 34 T 20S R 8E Longitude 36 10'04.53" N UTM E NAD 27
PERMIT/WAIVER No. DW-1327 Parcel No. 13934210033 Longitude 115 08'47.08" W N NAD 83 WGS 84

3 TYPE OF WELL
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock

Is this well being plugged because a replacement well was drilled? no
If yes, what is replacement well NOI? _____

Is there an existing well log? _____
If yes, what is NDWR well log #? _____

4 EXISTING WELL CONSTRUCTION
Depth Drilled 0 Feet Depth Cased 35 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>8</u>	<u>6</u>	<u>3/8</u>	<u>0</u>	<u>35</u>

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why: _____

Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no

If casing was left in place, please show where additional perforations were made:
Additional Perforations: _____

Existing Perforations:

Type of perforation	Size of perforation	From	To
<u>machine slotted</u>	<u>0.032</u>	<u>15</u> feet to	<u>35</u> feet

Type of perforator used:

From	To	Number of perfs per linear foot

5 WATER LEVEL
Static water level _____ feet below land surface
Artesian flow G.P.M. _____ P.S.I. _____
Water temperature _____ ° F Quality _____

8 WELL PLUGGING MATERIALS

From	To	Material Used	Pumped	Poured
<u>15</u>	<u>35</u>	<u>concrete grout</u>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>

6 Additional Notes or Comments

DW#2

Casing consumed by excavation: Contractor pulled casing, which was inside the excavation, during pump station foundation concrete pour. What little remaining bore hole was filled during pour.

**DO NOT DRILL
RECEIVED
JAN 09 2013
LAS VEGAS OFFICE**

Neat Cement Fluid Weight 94/7 lbs/gal
Bentonite Grout _____ % bentonite
Date Started 12/27/2012
Date Completed 12/27/2012

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Viking Drillers Inc Contractor
Address 801 Northport Dr. Contractor
Sacramento, CA 95691

Nevada contractor's license number _____
Issued by the State Contractor's Board 0034680

Nevada driller's license number issued by the Division of Water Resources, the on-site driller: _____

Signature [Signature]
Date 1/7/2013

Bombard
Need lic #

USE ADDITIONAL SHEETS IF NECESSARY

36.167954 - NAD 27
-115.145577



VIKING DRILLERS, INC.

Dewatering Systems

801 Northport Drive
West Sacramento, CA 95691-2153
(916) 372-4993 • FAX (916) 372-1337
www.vikingdrillersinc.com
California License #476668

January 7, 2013

Tracy Geter
Nevada Division of Water Resources
400 Shadow Lane, Suite 201
Las Vegas, NV 89106

RE: DW-1327 Well Completion Reports- Notice of Intent Card 35989

Dear Tracy:

Enclosed are the two (2) Well Completion Reports for the above NOI Card. These were temporary dewatering wells which were located at 300 S. Casino Center Blvd (Correction Center). These wells were installed within the excavation, due to the very tight construction area between the parking structure and the facility. When pouring the foundation for the new pump station, the contractor was forced to dig out the wells to create room for the pour, thus the wells were consumed by the excavation. I have included two (2) plugging reports for your records.

Respectfully,

VIKING DRILLERS, INC.


Sean LaChapelle
Estimator/Manager

DCNR/DWR
RECEIVED

JAN 09 2013

LAS VEGAS OFFICE