

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
**WELL DRILLER'S PLUGGING REPORT**

OFFICE USE ONLY  
Log No. 11662  
Permit No. 129  
Basin 129

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340  
*well name*

NOTICE OF INTENT NO. 67840 ✓

1. OWNER **Coeur Rochester Mine** ADDRESS AT WELL LOCATION **Packard and Buena Vista**  
MAILING ADDRESS **PO Box 1057** **Hydrographic Basins**  
**Lovelock, NV 89419** Subdivision Name: \_\_\_\_\_ County: **Pershing**

2. LOCATION **NW¼SE¼ Sec15T28N/ R34E** UTM E **402933**  NAD 27  
PERMIT/WAIVER NO. \_\_\_\_\_ Longitude **N 446380**  NAD 83/WGS 84  
Issued by Water Resources Parcel No. \_\_\_\_\_

3. TYPE OF WELL Is this well being plugged because a replacement well was drilled?  Yes  No  
 Domestic  Irrigation  Test  Municipal/Industrial  Monitor  Stock If yes, what is replacement well NOI? \_\_\_\_\_  
Is there an existing well log?  Yes  No If yes, what is NDWR well log #? **89459**

4. EXISTING WELL CONSTRUCTION  
Depth Drilled **154** Feet Depth Cased **147** Feet

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
4.00	2.06	.237	0	14

Existing Perforations:  
Type of perforation **Slotted**  
Size of perforation **.020**  
From **137** feet to **147** feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet

7. WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  Yes  No  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  Yes  No  
Was the casing pulled?  Yes  No  
Was the casing over drilled?  Yes  No  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforator used: **N/A**  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_

5. WATER LEVEL  
Static water level: **Dry** \_\_\_\_\_ feet below land surface  
Artesian flow: **N/A** G.P.M. **N/A** P.S.I.  
Water Temperature: **N/A** °F Quality **N/A**

8. WELL PLUGGING MATERIALS  
Material Used  
From **0** feet to **150** feet **Cement**  Pumped  Poured  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  Pumped  Poured

6. Additional Notes or Comments  
Materials used:  
**16 cu. ft. cement**

Neat Cement Fluid Weight **15.6** lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started **February 1, 2012**  
Date Completed **February 1, 2012**

9. DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name **Boart Longyear Drilling Services** (CONTRACTOR)  
Address **2745 California Avenue** (CONTRACTOR)  
**Salt Lake City, UT 84104**  
Nevada contractor's license number issued by the State Contractor's Board **002196**  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller **2376**

Signed \_\_\_\_\_  
By driller performing actual drilling on site or contractor  
Date **February 2, 2012**

2012 FEB 10 AM 11:15

*40.290179°N NAD27*  
*118.141959°W*

(Rev 05-06)

USE ADDITIONAL SHEETS IF NECESSARY