

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 116724
Permit No. _____
Basin 137B

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 70399

1. OWNER **Round Mountain Gold Corp** DV-11-36 ADDRESS AT WELL LOCATION **Round Mountain Mine, Round Mountain, NV.**
MAILING ADDRESS **P.O. Box 480** Round Mountain, NV. 89045
Subdivision Name: _____ County: **Nye**

2. LOCATION **SW¼NE¼ Sec30T10N/ R44E** Latitude _____ UTM E **492972** NAD 27
PERMIT/WAIVER NO. **M/O-1667** Longitude _____ N **4282947** NAD 83/WGS 84
Issued by Water Resources _____ Parcel. No. _____

3. TYPE OF WELL Domestic Irrigation Test Municipal/Industrial Monitor Stock
Is this well being plugged because a replacement well was drilled? Yes No
If yes, what is replacement well NOI? _____
Is there an existing well log? Yes No
If yes, what is NDWR well log #? **113723**

4. EXISTING WELL CONSTRUCTION
Depth Drilled **500** Feet Depth Cased **500** Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
2.375	.98	.218	+1	500

Existing Perforations:
Type of perforation **Slotted**
Size of perforation **.250**

From	feet to	feet
From 100	feet to	500 feet
From _____	feet to	_____ feet
From _____	feet to	_____ feet
From _____	feet to	_____ feet
From _____	feet to	_____ feet

5. WATER LEVEL
Static water level: **N/A** feet below land surface
Artesian flow: **N/A** G.P.M. **N/A** P.S.I.
Water Temperature: **N/A** °F Quality **N/A**

6. Additional Notes or Comments
Materials used: 70 bags neat cement 82.6 CuFt.

7. WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? Yes No
If well was not cleaned out to total depth, please explain why: _____

Was the well contaminated? Yes No
Was the casing pulled? Yes No
Was the casing over drilled? Yes No
If casing was left in place, please show where additional perforations were made:
Additional Perforations:
Type of perforator used: **NA**

From	feet to	feet	Number of perfs per linear foot
From _____	feet to	_____ feet	_____
From _____	feet to	_____ feet	_____
From _____	feet to	_____ feet	_____
From _____	feet to	_____ feet	_____
From _____	feet to	_____ feet	_____
From _____	feet to	_____ feet	_____

8. WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	Pumped	Poured
From 0	feet to	500 feet	Neat C.	<input type="checkbox"/>	<input checked="" type="checkbox"/>
From _____	feet to	_____ feet	_____	<input type="checkbox"/>	<input type="checkbox"/>
From _____	feet to	_____ feet	_____	<input type="checkbox"/>	<input type="checkbox"/>
From _____	feet to	_____ feet	_____	<input type="checkbox"/>	<input type="checkbox"/>
From _____	feet to	_____ feet	_____	<input type="checkbox"/>	<input type="checkbox"/>
From _____	feet to	_____ feet	_____	<input type="checkbox"/>	<input type="checkbox"/>

Neat Cement Fluid Weight **15.6** lbs/gal
Bentonite Grout _____ % bentonite

Date Started **May 18, 2013**
Date Completed **May 18, 2013**

9. DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name **Boart Longyear** (CONTRACTOR)
Address **2745 California Ave.** (CONTRACTOR)
SLC., UT. 84104
Nevada contractor's license number issued by the State Contractor's Board **0021976**
Nevada driller's license number issued by the Division of Water Resources, the on-site driller **2462**
Signed _____
By driller performing actual drilling on site or contractor
Date **June 4, 2013**

RECEIVED
2013 JUN -6 AM 11:48
STATE ENGINEERS OFFICE

Plugs original well log # 113723
NAD25
38.696982°N
117.080815°W