

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
Log No. 116961  
Permit No. \_\_\_\_\_  
Basin 028

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 67434

1 OWNER Allied Nevada Gold  
MAILING ADDRESS 9700 Gateway Dr Suite 200  
Reno, NV 89521

ADDRESS AT WELL LOCATION H13HR-003  
Subdivision Name: \_\_\_\_\_ County: Pershing

2 LOCATION sw 1/4 SW 1/4 Sec 1 T 34N N/S R 29 E  
PERMIT/WAIVER No. NV  
*Issued by Water Resources Parcel No.*

Latitude \_\_\_\_\_ UTM E 358549.06  NAD 27  
Longitude \_\_\_\_\_ N 4523034.82  NAD 83/WGS 84

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? no  
If yes, what is replacement well NOI? \_\_\_\_\_

Is there an existing well log? \_\_\_\_\_  
If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
Depth Drilled \_\_\_\_\_ Feet Depth Cased \_\_\_\_\_ Feet

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)

If well was not cleaned out to total depth, please explain why: \_\_\_\_\_  
Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no

Existing Perforations:  
Type of perforation \_\_\_\_\_  
Size of perforation \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet

If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforater used: \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_

5 WATER LEVEL  
Static water level 452 feet below land surface  
Artesian flow no G.P.M. \_\_\_\_\_ P.S.I. \_\_\_\_\_  
Water temperature 103 °F Quality \_\_\_\_\_ poor

8 WELL PLUGGING MATERIALS  
Material Used  
From 0 feet to 20 feet neat cement  Pumped  Poured  
From 20 feet to 280 feet 3/8 bentonite chip  Pumped  Poured  
From 280 feet to 1220 feet abandonite  Pumped  Poured  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet \_\_\_\_\_  Pumped  Poured  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet \_\_\_\_\_  Pumped  Poured  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet \_\_\_\_\_  Pumped  Poured

6 Additional Notes or Comments  
This was an exploration borehole #4793

RECEIVED  
2013 JUN 24 AM 11:33  
STATE ENGINEERS OFFICE  
  
NAD 27  
40.9462626  
113.6769816

Neat Cement Fluid Weight 16 lbs/gal  
Bentonite Grout 30 % bentonite  
Date Started 6/6/2013  
Date Completed 6/14/2013

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name National EWP Contractor  
Address 580 W Silver St Contractor  
Elko, NV 89801  
Nevada contractor's license number \_\_\_\_\_  
issued by the State Contractor's Board 0075355  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2470  
Signed \_\_\_\_\_  
By driller performing actual drilling on site or contractor  
Date 6/17/2013