

**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**

**OFFICE USE ONLY**  
Log No. 117067  
Permit No. \_\_\_\_\_  
Basin 212

**PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 36895

1 OWNER City of N. Las Vegas- Public Right Way ADDRESS AT WELL LOCATION West Bound Lake Mead Between  
MAILING ADDRESS 2200 Constitution Wy 12012 Losee & I-15  
N. Las Vegas, NV 89030 Subdivision Name: \_\_\_\_\_ County: Clark

2 LOCATION SW  $\frac{1}{4}$  NE  $\frac{1}{4}$  Sec 22 T 20S N/S R 61 E Latitude 36 11'45.23010"N UTM E  NAD 27  
PERMIT/WAIVER No. DW-1326 139-22-699-022 Longitude 115 08'31.18311"W N  NAD 83/WGS 84  
Issued by Water Resources Parcel No.

3 TYPE OF WELL  Domestic  Irrigation  Test  Municipal/Industrial  Monitor  Stock  
Is this well being plugged because a replacement well was drilled? NO  
If yes, what is replacement well NO? \_\_\_\_\_  
Is there an existing well log? N/A  
If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 30 Feet Depth Cased 30 Feet

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
10.75		Sch 40	0	30

Existing Perforations:

Type of perforation	Factory Slotted
Size of perforation <u>15</u>	<u>0.06</u>
From _____ feet to _____ feet	<u>30</u> feet
From _____ feet to _____ feet	_____ feet
From _____ feet to _____ feet	_____ feet
From _____ feet to _____ feet	_____ feet
From _____ feet to _____ feet	_____ feet

5 WATER LEVEL  
Static water level 16.45 feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

6 Additional Notes or Comments  
Knocked out bottom, tremie from bottom up, pulled casing, top off as needed

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made: \_\_\_\_\_

Additional Perforations:

Type of perforator used:	From	feet to	feet	Number of perfs per linear foot
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
0	30	feet	Cement	<input checked="" type="checkbox"/>	<input type="checkbox"/>
_____	_____	feet	_____	<input type="checkbox"/>	<input type="checkbox"/>
_____	_____	feet	_____	<input type="checkbox"/>	<input type="checkbox"/>
_____	_____	feet	_____	<input type="checkbox"/>	<input type="checkbox"/>
_____	_____	feet	_____	<input type="checkbox"/>	<input type="checkbox"/>
_____	_____	feet	_____	<input type="checkbox"/>	<input type="checkbox"/>

Neat Cement Fluid Weight 94/5.2 lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite

Date Started 6-Feb  
Date Completed 2/6/2013

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Cascade Drilling L.P.  
Contractor

Address 4590 Copper Sage St  
Contractor

Las Vegas, NV 89115

Nevada contractor's license number issued by the State Contractor's Board C23-0073966

Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2381

Signed \_\_\_\_\_  
By driller performing actual drilling on site or contractor

Date 2-25-13