

**STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT**

OFFICE USE ONLY
Log No. 117069
Permit No. _____
Basin 212

**PRINT OR TYPE ONLY
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 36899

| | | | |
|---|---------------------------------|--|---|
| 1 OWNER <u>Vegas Construction LLC</u> | | ADDRESS AT WELL LOCATION <u>2308 S. Las Vegas Blvd</u> | |
| MAILING ADDRESS <u>9803 San Fernando Rd</u> | | <u>SVE-3</u> <u>Las Vegas</u> | |
| <u>Pacolma, CA 91331-2604</u> | | Subdivision Name: _____ County: <u>Clark</u> | |
| 2 LOCATION <u>SE ¼ SE ¼ Sec 4 T 21S N/S R 61 E</u> | Latitude <u>36 08'42.84"N</u> | UTM E | <input type="checkbox"/> NAD 27 |
| PERMIT/WAIVER No. <u>R-1592</u> <u>162-04-813-110</u> | Longitude <u>115 09'23.52"W</u> | N | <input checked="" type="checkbox"/> NAD 83/WGS 84 |
| <small>Issued by Water Resources</small> | <small>Parcel No.</small> | | |

| | | | |
|---|---|--|---|
| 3 TYPE OF WELL | | Is this well being plugged because a replacement well was drilled? <u>NO</u> | Is there an existing well log? <u>N/A</u> |
| <input type="checkbox"/> Domestic | <input type="checkbox"/> Irrigation | <input type="checkbox"/> Test | |
| <input type="checkbox"/> Municipal/Industrial | <input checked="" type="checkbox"/> Monitor | <input type="checkbox"/> Stock | |
| | | If yes, what is replacement well NOI? _____ | If yes, what is NDWR well log #? _____ |

| | | | |
|-------------------------------|----------------------------|-------------------------|-----------------------|
| 4 EXISTING WELL CONSTRUCTION | | | |
| Depth Drilled <u>N/A</u> Feet | Depth Cased <u>13</u> Feet | | |
| EXISTING CASING SCHEDULE | | | |
| Size O.D. (Inches) | Weight/Ft. (Pounds) | Wall Thickness (Inches) | From (Feet) To (Feet) |
| <u>2.375</u> | | <u>Sch 40</u> | <u>0</u> <u>13</u> |

| | |
|--|--|
| 7 WELL PLUGGING PROCEDURE | |
| Was well cleaned out to total depth? <input checked="" type="checkbox"/> yes <input type="checkbox"/> no | If well was not cleaned out to total depth, please explain why: _____ |
| Was the well contaminated? <input type="checkbox"/> yes <input checked="" type="checkbox"/> no | Was the casing pulled? <input type="checkbox"/> yes <input checked="" type="checkbox"/> no |
| Was the casing over drilled? <input type="checkbox"/> yes <input checked="" type="checkbox"/> no | If casing was left in place, please show where additional perforations were made: _____ |

Existing Perforations:

| | | |
|---------------------|-------------------------------|------------|
| Type of perforation | <u>N/A</u> | |
| Size of perforation | From _____ feet to _____ feet | _____ feet |
| From _____ | _____ feet to _____ feet | _____ feet |
| From _____ | _____ feet to _____ feet | _____ feet |
| From _____ | _____ feet to _____ feet | _____ feet |
| From _____ | _____ feet to _____ feet | _____ feet |

Additional Perforations:


| | | |
|-------------------------------|---------------------------------------|--|
| Type of perforator used: | <u>N/A</u> | |
| From _____ feet to _____ feet | Number of perfs per linear foot _____ | |
| From _____ feet to _____ feet | Number of perfs per linear foot _____ | |
| From _____ feet to _____ feet | Number of perfs per linear foot _____ | |
| From _____ feet to _____ feet | Number of perfs per linear foot _____ | |
| From _____ feet to _____ feet | Number of perfs per linear foot _____ | |
| From _____ feet to _____ feet | Number of perfs per linear foot _____ | |

| | |
|--|---|
| 5 WATER LEVEL | |
| Static water level <u>11.5</u> feet below land surface | Artesian flow _____ G.P.M. _____ P.S.I. |
| Water temperature _____ °F | Quality _____ |

| | | | |
|--------------------------------------|-----------------|--|--|
| 8 WELL PLUGGING MATERIALS | | | |
| From <u>1</u> feet to <u>13</u> feet | <u>Cement</u> | <input checked="" type="checkbox"/> Pumped | <input type="checkbox"/> Poured |
| From <u>0</u> feet to <u>1</u> feet | <u>Concrete</u> | <input type="checkbox"/> Pumped | <input checked="" type="checkbox"/> Poured |
| From _____ feet to _____ feet | | <input type="checkbox"/> Pumped | <input type="checkbox"/> Poured |
| From _____ feet to _____ feet | | <input type="checkbox"/> Pumped | <input type="checkbox"/> Poured |
| From _____ feet to _____ feet | | <input type="checkbox"/> Pumped | <input type="checkbox"/> Poured |
| From _____ feet to _____ feet | | <input type="checkbox"/> Pumped | <input type="checkbox"/> Poured |

| | |
|---|--|
| 6 Additional Notes or Comments | |
| <u>Tremie Neat Cement form bottom up, Pressure Grout Well</u> | |
| <u>Top off as needed, Concrete cap</u> | |

| | |
|--|-----------------------------------|
| Neat Cement Fluid Weight <u>94/5.2</u> lbs/gal | Bentonite Grout _____ % bentonite |
| Date Started _____ | <u>13-Feb</u> |
| Date Completed _____ | <u>2/13/2013</u> |

| | |
|--|--|
| 9 DRILLER'S CERTIFICATION | |
| This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge. | |
| Name | <u>Cascade Drilling L.P.</u> |
| Address | <u>4590 Copper Sage St</u> |
| | <u>Las Vegas, NV 89115</u> |
| Nevada contractor's license number issued by the State Contractor's Board | <u>C23-0073966</u> |
| Nevada driller's license number issued by the Division of Water Resources, the on-site driller | <u>2381</u> |
| Signed |  |
| Date | <u>2-27-13</u> |