

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
Log No. 117198  
Permit No. \_\_\_\_\_  
Basin 2161

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 37034

1 OWNER USA Washington dc  
MAILING ADDRESS \_\_\_\_\_

ADDRESS AT WELL LOCATION Unincorp. County (creech afb)  
Subdivision Name: \_\_\_\_\_ County: Clark

2 LOCATION SE ¼ SE ¼ Sec 4 T 16S N/S R 56 E  
PERMIT/WAIVER No. H-000020 059-03-000-005  
Issued by Water Resources Parcel No.

Latitude 36.581688 UTM E  NAD 27  
Longitude 115.655747 N  NAD 83/WGS 84

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? \_\_\_\_\_  
If yes, what is replacement well NOI? \_\_\_\_\_  
Is there an existing well log? yes  
If yes, what is NDWR well log #? 41220

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 61 Feet Depth Cased 60 Feet

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
2.5		0.18	0	60

Existing Perforations:

Type of perforation	sch	From	To
sch 80pvc	0.02	30	60
From		feet to	feet
From		feet to	feet
From		feet to	feet
From		feet to	feet

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations:

Type of perforator used: pulled casing

From	To	Number of perfs per linear foot
From	feet to	feet

5 WATER LEVEL  
Static water level 38 feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

From	To	Material Used	Pumped	Poured
From <u>0</u>	feet to <u>60</u>		<input type="checkbox"/>	<input type="checkbox"/>
From	feet to		<input type="checkbox"/>	<input type="checkbox"/>
From	feet to		<input type="checkbox"/>	<input type="checkbox"/>
From	feet to		<input type="checkbox"/>	<input type="checkbox"/>
From	feet to		<input type="checkbox"/>	<input type="checkbox"/>
From	feet to		<input type="checkbox"/>	<input type="checkbox"/>

6 Additional Notes or Comments  
DCNR/DWR/SNBO RECEIVED  
APR 10 2013  
remorale well box  
pulled casing  
filled from botton  
to top with cement  
mw98  
3961302r

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 3/27/2013  
Date Completed 3/27/2013

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Eagle Drilling LLC. Contractor  
Address 7150 Placid St., Las Vegas, Nv., 89119 Contractor  
Nevada contractor's license number \_\_\_\_\_ issued by the State Contractor's Board 51266  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2097  
Signed \_\_\_\_\_  
By driller performing actual drilling on site or contractor  
Date 4/9/2013

USE ADDITIONAL SHEETS IF NECESSARY

36.5817274 NAD 21  
-115.6548938

(Rev. 05-00)