

STATE OF NEVADA  
 DIVISION OF WATER RESOURCES  
 WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
 Log No. 117396  
 Permit No. \_\_\_\_\_  
 Basin 212

PRINT OR TYPE ONLY  
 DO NOT WRITE ON BACK

Please complete this form in its entirety in  
 accordance with NRS 534.170 and NAC 534.340

1 OWNER Metroflag Cable LLC ADDRESS AT WELL LOCATION 3755 S. Las Vegas Blvd.  
 MAILING ADDRESS 3743 S. Las Vegas Blvd #204 Subdivision Name: \_\_\_\_\_ County: Clark  
Las Vegas NV 89109  
 2 LOCATION NW 1/4 SW 1/4 Sec 21 T 21 N R 61 E Latitude 36°06'21.9" UTM E \_\_\_\_\_  NAD 27  
 PERMIT/WAIVER No. 162.21.301.018 Longitude -115°10'21.2" N \_\_\_\_\_  NAD 83/WGS 84  
 Issued by Water Resources Parcel No. \_\_\_\_\_

3 TYPE OF WELL Is this well being plugged because a replacement well was drilled? NO Is there an existing well log? NO  
 Domestic  Irrigation  Test  Municipal/Industrial  Monitor  Stock If yes, what is replacement well NOI? \_\_\_\_\_ If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
 Depth Drilled 33 Feet 33 Depth Cased 33 Feet  
 EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>2</u>	<u>PVC</u>	<u>Sch 40</u>	<u>0</u>	<u>33</u>

7 WELL PLUGGING PROCEDURE  
 Was well cleaned out to total depth?  yes  no  
 If well was not cleaned out to total depth, please explain why: \_\_\_\_\_  
 Was the well contaminated?  yes  no  
 Was the casing pulled?  yes  no  
 Was the casing over drilled?  yes  no  
 If casing was left in place, please show where additional perforations were made:  
 Additional Perforations: \_\_\_\_\_  
 Type of perforator used: None

Existing Perforations:  
 Type of perforation Factory slot  
 Size of perforation 2" 0.20"

From	feet to	feet	feet
<u>8'</u>	<u>33'</u>		

From	feet to	feet	Number of perfs per linear foot

5 WATER LEVEL  
 Static water level 16' feet below land surface  
 Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
 Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	<input type="checkbox"/> Pumped	<input checked="" type="checkbox"/> Poured
<u>33'</u>	<u>15'</u>	<u>15'</u>	<u>hole plug</u>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
<u>15'</u>	<u>0'</u>	<u>0'</u>	<u>Cement</u>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>

6 Additional Notes or Comments  
2" PVC was pulled then hole was drilled out to 33' then hole plugged to above water table the cemented to surface.

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
 Bentonite Grout \_\_\_\_\_ % bentonite  
 Date Started 8/1/13  
 Date Completed 8/1/13

DCNR/DWR/SNBO RECEIVED  
 AUG 05 2013

9 DRILLER'S CERTIFICATION  
 This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
 Name Elite Drilling Inc. Contractor  
 Address 4255 W. Post Rd. Contractor  
Las Vegas, NV 89118  
 Nevada contractor's license number issued by the State Contractor's Board 0054931  
 Nevada driller's license number issued by the Division of Water Resources, the on-site driller M-1869  
 Signed \_\_\_\_\_ By driller performing actual drilling on-site or contractor  
 Date 8/2/13