

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S REPORT

OFFICE USE ONLY
Log No. 117559
Permit No. V10479
Basin No. 105

PRINT OR TYPE IN BLACK INK ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 69899
WELL NAME (if applicable): _____

1. OWNER/CLIENT NAME Flying Eagle Ranch
MAILING ADDRESS 850 Flying Eagle Ranch Gv NV 89460

DETAILED ADDRESS AT WELL LOCATION Carson River Basin

Subdivision Name: _____ County: Douglas

2. PLS LOCATION SE 1/4 SW 1/4 13 Sec 12 N/S 19 E
PERMIT/WAIVER NO. V010479 1219-13-000-032
Issued by Water Resources Current Parcel No.

Latitude 38 53.843 UTM E NAD 27
Longitude 119 48.090 UTM N NAD 83/WGS 84

3. WORKED PERFORMED
 New Well Deepen: Orig WL# _____
 Replacement: Original well log # _____
 Recondition: Original well log # _____

4. PROPOSED USE
 Domestic Irrigation Monitor
 Mining / Dewater Com / Ind Stock
 Test / Other Mun / QM Rec

5. WELL TYPE
 Auger Rotary RVC
 Air Mud Sonic
 Other

6. LITHOLOGIC LOG					
Material Encountered	Lost Circ.	Water Strata	From	To	Thick-ness
Soil clay			0	10	10
Clay			10	16	6
Black sand gravel			16	90	74
sand gravel			90	160	70
REPLACES UNKNOWN WELL LOG NAD 27 38.897475° N 119.800489° W					

9. WELL CONSTRUCTION
Depth Drilled: 160 Feet Depth Cased: 160 Feet

HOLE DIAMETER (BIT SIZE)					
From		To			
<u>10 5/8</u>	Inches	<u>0</u>	Feet	<u>160</u>	Feet
	Inches		Feet		Feet
	Inches		Feet		Feet

CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>6 5/8</u>	<u>12</u>	<u>.188</u>	<u>+2</u>	<u>18</u>
<u>6</u>	<u>SDR21</u>		<u>18</u>	<u>160</u>

PERFORATIONS:
Type of perforation: Factory Screen
Size of perforation: 3/32"
From 120 Feet To 160 Feet
From _____ Feet To _____ Feet
From _____ Feet To _____ Feet

ANNULAR MATERIALS
 Sanitary Seal 0 to 103 Pumped Poured
 Neat Cement _____ to _____ Pumped Poured
 Cement Grout 0 to 103 Pumped Poured
 Concrete Grout _____ to _____ Pumped Poured
 Bentonite Chips _____ to _____ Pumped Poured
 Bentonite Grout _____ to _____ Pumped Poured
 15 % 20 % Other, explain: _____
 Gravel Pack [> 0.2 in.] 103 to 160 Pumped Poured
 Sand Pack [< 0.2 in.] _____ to _____ Pumped Poured
 Other, explain: _____ to _____ Pumped Poured

Date started: 2-Aug, 20 13
Date completed: 8/5/2013, 20 20

7. WATER QUALITIES
Static water level: Artesian Feet below land surface
Artesian Flow: 2gpm G.P.M. _____ P.S.I.
Water Temperature: cold ° Fahrenheit
Water Quality: clear

10. DRILLER'S CERTIFICATION
This well was drilled under my supervision. This report is true to the best of my knowledge.
Name Blain Drilling Contractor
Address PO 1255 CC NV 89702 Contractor

8. WELL TEST DATA			
Test Method:	G.P.M.	Draw Down (Feet Below Static)	Recorded Time (Hours)
<input type="checkbox"/> Bailer <input type="checkbox"/> Pump <input checked="" type="checkbox"/> Air Lift	<u>45</u>		<u>2hours</u>

Nevada contractor's license number as issued by the State Contractor's Board: 46498A
Nevada well driller's license number as issued by the Nevada Division of Water Resources (on-site driller): 2134
Signed: _____
By driller performing actual drilling on site or contractor
Date: 8/12/2013