

ORIGINAL

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 118008
Permit No. _____
Basin Φ 31

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 68527

1 OWNER BLM
MAILING ADDRESS 1340 Financial Blvd
Reno, NV

ADDRESS AT WELL LOCATION Barbara Worth Well - historical monument
Subdivision Name: _____ County: Humboldt

2 LOCATION SW ¼ NW ¼ Sec 2 T 36N N/S R 34 E
PERMIT/WAIVER No. _____
Issued by Water Resources. Parcel No.

Latitude 41° 01.616 N UTM E NAD 27
Longitude 118° 08.216 W N NAD 83/WGS 84

3 TYPE OF WELL
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock

Is this well being plugged because a replacement well was drilled? NO
If yes, what is replacement well NOI? _____

Is there an existing well log? NO
If yes, what is NDWR well log #? _____

4 EXISTING WELL CONSTRUCTION
Depth Drilled N/A Feet Depth Cased 60' Feet

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
6"			0'	60'

If well was not cleaned out to total depth, please explain why: _____
Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no

Existing Perforations:

Type of perforation	Size of perforation	From	feet to	feet

If casing was left in place, please show where additional perforations were made:
Additional Perforations:

Type of perforater used:	From	feet to	feet	Number of perfs per linear foot

5 WATER LEVEL
Static water level DRY feet below land surface
Artesian flow NO G.P.M. 0 P.S.I.
Water temperature N/A °F Quality _____

8 WELL PLUGGING MATERIALS

6 Additional Notes or Comments
This well is considered a historical marker so we did the least amount of disturbance possible to the ground around the well location, PER BLM.
There is no well log that could be found so we tagged the hole at 60' and pumped neat cement to ground surface
I SPOKE WITH MATT HEIN ON THIS SITUATION AND WAS GIVEN HIS APPROVAL ON THIS ABANDONMENT.

From	feet to	feet	Material Used	<input checked="" type="checkbox"/> Pumped	<input type="checkbox"/> Poured
0'	60'	feet	NEAT CEMENT	<input checked="" type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>

Neat Cement Fluid Weight 15 LBS lbs/gal
Bentonite Grout _____ % bentonite
Date Started 7/11/2012
Date Completed 7/11/2012

RECEIVED
2012 AUG -9 AM 11:15
STATE ENGINEERS OF FL

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name Hydro Resources - West, Inc. Contractor
Address 4975 W. Winnemucca Blvd. Contractor
Winnemucca, NV 89445
Nevada contractor's license number _____
issued by the State Contractor's Board 56797
Nevada driller's license number issued by the _____
Division of Water Resources, the on-site driller # 2177
Signed Michelle Strother
By driller performing actual drilling on site or contractor
Date 7/16/2012

41.027031°N
118.135955°W
NAD27

USE ADDITIONAL SHEETS IF NECESSARY