

**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**

**OFFICE USE ONLY**

Log No. 118046

Permit No. \_\_\_\_\_

Basin 101

**PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 68465

1 OWNER +Michelle Gulden  
Gary Goudea ADDRESS AT WELL LOCATION 790 Wetland View

MAILING ADDRESS 790 Wetland View Fallon NV 89406 Subdivision Name: \_\_\_\_\_ County: Churchill

2 LOCATION SW 1/4 SW 1/4 Sec 29 T 19 N/R 28 E Latitude 0339283 UTM E 0339283  NAD 27

PERMIT/WAIVER No. 008-652-36 Longitude \_\_\_\_\_ N 4371307  NAD 83/WGS 84

Issued by Water Resources \_\_\_\_\_ Parcel No. \_\_\_\_\_

3 TYPE OF WELL  Domestic  Irrigation  Test  Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? yes

Is there an existing well log? ADA None

If yes, what is replacement well NDI? 68464 If yes, what is NDWR well log #? 63954

4 EXISTING WELL CONSTRUCTION

Depth Drilled	Feet	Depth Cased	Feet
EXISTING CASING SCHEDULE			
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet) To (Feet)
<u>6 5/8</u>	<u>12.9</u>	<u>1.88</u>	<u>+1</u> <u>104</u>

7 WELL PLUGGING PROCEDURE

Was well cleaned out to total depth?  yes  no

If well was not cleaned out to total depth, please explain why: washed in trimmy pipe hit fill @ 78 FT. Washed fill out 78-104 hit something hard @ 104 clients recalls well depth of 100 FT

Was the well contaminated?  yes  no

Was the casing pulled?  yes  no

Was the casing over drilled?  yes  no

If casing was left in place, please show where additional perforations were made:

Existing Perforations:

Type of perforation	Size of perforation	From	feet to	feet
?	?			

Additional Perforations:

Type of perforator used: Holt Perforator (mechanical)

From	feet to	feet	Number of perms per linear foot
<u>50</u>	<u>104</u>	<u>feet</u>	<u>2</u>

5 WATER LEVEL

Static water level 40' feet below land surface

Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.

Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
<u>0</u>	<u>104</u>	<u>feet</u>	<u>neat cement</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>

6 Additional Notes or Comments

**RECEIVED  
2012 SEP - 7 AM 10:10  
STATE ENGINEERS OF NEVADA**

Neat Cement Fluid Weight 14.8 lbs/gal

Bentonite Grout \_\_\_\_\_ % bentonite

Date Started 8-28-2012

Date Completed 8-28-2012

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Weisco Drilling Contractor

Address P.O. Box 888 Contractor

Fallon NV 89406

Nevada contractor's license number issued by the State Contractor's Board 11752

Nevada driller's license number issued by the Division of Water Resources, the on-site driller 1727

Signed 8-31-2012 By driller performing actual drilling on site or contractor

Date Dave Anderson