

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
Log No. 118128  
Permit No. \_\_\_\_\_  
Basin 212

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 37087

1 OWNER USA ADDRESS AT WELL LOCATION Sunrise Manor [ Nellis A.F.B.]  
MAILING ADDRESS Washington DC  
Subdivision Name: \_\_\_\_\_ County: Clark

2 LOCATION SW ¼ SW ¼ Sec 3 T 20S N/S R 62 E Latitude 36.234907 UTM E  NAD 27  
PERMIT/WAIVER No. H-000078 140-03-301-001 Longitude 115.042985 N  NAD 83/WGS 84  
Issued by Water Resources Parcel No. \_\_\_\_\_

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock  
Is this well being plugged because a replacement well was drilled? \_\_\_\_\_  
If yes, what is replacement well NOI? \_\_\_\_\_  
Is there an existing well log? no  
If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 80 Feet Depth Cased 80 Feet  
EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>10</u>	<u>pvc</u>	<u>40sch</u>	<u>0</u>	<u>80</u>

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_  
Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforator used: try to pull casing and knocked out bottom

Existing Perforations:  
Type of perforation Factory  
Size of perforation 0.02

From	Size	feet to	To	feet
From	<u>40</u>	feet to	<u>50</u>	feet
From	<u>70</u>	feet to	<u>80</u>	feet
From		feet to		feet
From		feet to		feet

From	feet to	feet	Number of perfs per linear foot
From			

5 WATER LEVEL  
Static water level 41 feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

6 Additional Notes or Comments  
try to pull casing  
knocked out bottom  
**DCNR/DWR/SNBO**  
**RECEIVED**  
**SEP 17 2013**  
tremied  
filled from botton  
to top  
3961302 gcw-1

From	feet to	feet	Material Used	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From	<u>20</u>	feet to	<u>80</u> feet quik grout	<input checked="" type="checkbox"/>	<input type="checkbox"/>
From	<u>0</u>	feet to	<u>20</u> feet concrete mix	<input type="checkbox"/>	<input checked="" type="checkbox"/>
From		feet to		<input type="checkbox"/>	<input type="checkbox"/>
From		feet to		<input type="checkbox"/>	<input type="checkbox"/>
From		feet to		<input type="checkbox"/>	<input type="checkbox"/>
From		feet to		<input type="checkbox"/>	<input type="checkbox"/>

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 8/18/2013  
Date Completed 8/18/2013

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Eagle Drilling LLC.  
Contractor  
Address 7150 Placid St., Las Vegas, Nv., 89119  
Contractor  
Nevada contractor's license number \_\_\_\_\_  
issued by the State Contractor's Board 51266  
Nevada driller's license number issued by the Division of Water Resources, the on site driller 2097  
Signed \_\_\_\_\_  
By driller performing actual drilling on site or contractor  
Date 8/21/2013