

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 118131
Permit No. _____
Basin 212

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 37083

1 OWNER USA ADDRESS AT WELL LOCATION Sunrise Manor [Nellis A.F.B.]
MAILING ADDRESS Washington DC
Subdivision Name: _____ County: Clark

2 LOCATION NE ¼ NW ¼ Sec 10 T 20S N/S R 62 E Latitude 36.233201 UTM E NAD 27
PERMIT/WAIVER No. H-000078 140-10-101-001 Longitude 115.038425 N NAD 83/WGS 84
Issued by Water Resources Parcel No. _____

3 TYPE OF WELL
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock
Is this well being plugged because a replacement well was drilled? _____
If yes, what is replacement well NOI? _____
Is there an existing well log? no
If yes, what is NDWR well log #? _____

4 EXISTING WELL CONSTRUCTION
Depth Drilled 70 Feet Depth Cased 70 Feet
EXISTING CASING SCHEDULE

| Size O.D. (Inches) | Weight/Ft. (Pounds) | Wall Thickness (Inches) | From (Feet) | To (Feet) |
|--------------------|---------------------|-------------------------|-------------|-----------|
| <u>4</u> | <u>pvc</u> | <u>40sch</u> | <u>0</u> | <u>70</u> |
| | | | | |
| | | | | |
| | | | | |

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why: _____
Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no
If casing was left in place, please show where additional perforations were made: _____

Existing Perforations:
Type of perforation Factory
Size of perforation 0.02

| From | feet to | feet | feet |
|-----------|-----------|-----------|-----------|
| <u>40</u> | <u>70</u> | <u>70</u> | <u>70</u> |
| | | | |
| | | | |
| | | | |
| | | | |

Additional Perforations:
Type of perforator used: try to pull casing and knocked out bottom

| From | feet to | feet | Number of perfs per linear foot |
|------|---------|------|---------------------------------|
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

5 WATER LEVEL
Static water level 43 feet below land surface
Artesian flow _____ G.P.M. _____ P.S.I.
Water temperature _____ °F Quality _____

8 WELL PLUGGING MATERIALS

6 Additional Notes or Comments
try to pull casing
knocked out bottom
tremied
filled from bottom
to top
DCNR/DWR/SNBC
RECEIVED
SEP 17 2013

| From | feet to | feet | Material Used | <input checked="" type="checkbox"/> Pumped | <input type="checkbox"/> Poured |
|-----------|-----------|-----------|---------------------|--|-------------------------------------|
| <u>20</u> | <u>70</u> | <u>70</u> | <u>quik grout</u> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| <u>0</u> | <u>20</u> | <u>20</u> | <u>concrete mix</u> | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| | | | | <input type="checkbox"/> | <input type="checkbox"/> |
| | | | | <input type="checkbox"/> | <input type="checkbox"/> |
| | | | | <input type="checkbox"/> | <input type="checkbox"/> |
| | | | | <input type="checkbox"/> | <input type="checkbox"/> |

Neat Cement Fluid Weight _____ lbs/gal
Bentonite Grout _____ % bentonite
Date Started 8/17/2013
Date Completed 8/17/2013

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name Eagle Drilling LLC.
Contractor
Address 7150 Placid St., Las Vegas, Nv., 89119
Contractor
Nevada contractor's license number issued by the State Contractor's Board 51266
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2007 2272
Signed [Signature]
By driller performing actual drilling on site or contractor
Date 8/21/2013