

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 118134
Permit No. _____
Basin 212

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 37750

1 OWNER USA ADDRESS AT WELL LOCATION Sunrise Manor [Nellis A.F.B.]
MAILING ADDRESS Washington DC Subdivision Name: _____ County: Clark

2 LOCATION SW ¼ SW ¼ Sec 3 T 20S N/S R 62 E Latitude 36.235552 UTM E NAD 27
PERMIT/WAIVER No. H-000078 140-03-301-001 Longitude 115.039060 N NAD 83/WGS 84
Issued by Water Resources Parcel No.

3 TYPE OF WELL Is this well being plugged because a replacement well was drilled? Is there an existing well log? no
 Domestic Irrigation Test Stock
 Municipal/Industrial Monitor Stock
If yes, what is replacement well NOI? If yes, what is NDWR well log #?

4 EXISTING WELL CONSTRUCTION
Depth Drilled 65 Feet Depth Cased 65 Feet

| EXISTING CASING SCHEDULE | | | | |
|--------------------------|---------------------|-------------------------|-------------|-----------|
| Size O.D. (Inches) | Weight/Ft. (Pounds) | Wall Thickness (Inches) | From (Feet) | To (Feet) |
| <u>4</u> | <u>pvc</u> | <u>40sch</u> | <u>0</u> | <u>65</u> |
| | | | | |
| | | | | |

Existing Perforations:
Type of perforation Factory
Size of perforation 0.02
From 35 feet to 65 feet
From _____ feet to _____ feet

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why: _____

Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no
If casing was left in place, please show where additional perforations were made:
Additional Perforations:
Type of perforator used: try to pull casing and knocked out bottom
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____

5 WATER LEVEL
Static water level 43 feet below land surface
Artesian flow _____ G.P.M. _____ P.S.I.
Water temperature _____ °F Quality _____

8 WELL PLUGGING MATERIALS

| Material Used | | | | | |
|---------------------------------------|---------------------|--|--|--|--|
| From <u>20</u> feet to <u>65</u> feet | <u>quik grout</u> | <input checked="" type="checkbox"/> Pumped | <input type="checkbox"/> Poured | | |
| From <u>0</u> feet to <u>20</u> feet | <u>concrete mix</u> | <input type="checkbox"/> Pumped | <input checked="" type="checkbox"/> Poured | | |
| From _____ feet to _____ feet | | <input type="checkbox"/> Pumped | <input type="checkbox"/> Poured | | |
| From _____ feet to _____ feet | | <input type="checkbox"/> Pumped | <input type="checkbox"/> Poured | | |
| From _____ feet to _____ feet | | <input type="checkbox"/> Pumped | <input type="checkbox"/> Poured | | |
| From _____ feet to _____ feet | | <input type="checkbox"/> Pumped | <input type="checkbox"/> Poured | | |

6 Additional Notes or Comments

try to pull casing
DCNR/DWR/SNBO knocked out bottom
RECEIVED
SEP 17 2013
tremied
filled from botton
to top
3961302 44mw-20

Neat Cement Fluid Weight _____ lbs/gal
Bentonite Grout _____ % bentonite
Date Started 8/15/2013
Date Completed 8/15/2013

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name Eagle Drilling LLC. Contractor
Address 7150 Placid St., Las Vegas, Nv., 89119 Contractor
Nevada contractor's license number issued by the State Contractor's Board 51266
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2097
Signed _____
By driller performing actual drilling at site of contractor
Date 8/21/2013

(Rev. 05-06) USE ADDITIONAL SHEETS IF NECESSARY

36.235552 NAD 27
-115.0382257